

February 22, 2011

Illinois Environmental Protection Agency Permit Section, Division of Water Pollution Control P.O. Box 19276 Springfield, IL 62794-9276

Subject: Leachate Connection to Sanitary Sewer Forcemain

Mallard North Landfill

Forest Preserve District of DuPage County, Illinois

Dear Sir/Madam:

On behalf of the Forest Preserve District of DuPage County (FPD), RMT, Inc. (RMT) is submitting the attached Application for Permit or Construction Approval form WPC-PS-1, Schedules A/B, F, and N for the connection of the Mallard North Landfill (MNL) leachate collection system to an existing sanitary force main owned and operated by the Village of Hanover Park. The Village of Hanover Park has agreed to accept the leachate from MNL. We understand that there will be no review fee, since the FPD is a unit of government.

The MNL is owned by the FPD and is located in unincorporated DuPage County, near the village of Hanover Park. The site is located just south of Greenbrook Boulevard, north of the West Branch of the DuPage River (WBDR), and north of the Mallard Lake Landfill (see Figure 1).

The FPD currently collects leachate from the landfill with three pneumatic pumps for temporary storage in an above grade tank. A tank truck collects leachate daily from the tank for treatment at a local wastewater treatment plant. In order to reduce leachate disposal costs, the FPD plans to construct a small diameter leachate forcemain from the MNL site south to a lift station (refer to Figure 3), and then to the existing Village of Hanover Park 16-inch-diameter sanitary forcemain located south of the WBDR (refer to Figures 1 and 2). The FPD plans to construct the leachate connection in spring 2011.

Erosion controls will be used as noted on Figure 4. The project will not be located in the 100-year flood plain or in a wetland (maps are attached).

II \ WPMSN\PJT1\01793\01\005\LBI79304005-002.DOCX

Illinois Environmental Protection Agency February 22, 2011 Page 2

Please review the application information and prepare the necessary permit. Your assistance is appreciated. Please call me at (608) 662-5121 office, or 608-358-5215 (cell), if you have any questions.

Sincerely,

RMT, Inc.

Jan C. Kucher, P.E. Senior Engineer

Attachments: Attachment 1: Application for Permit or Construction Approval (WPC-PS-1)

Schedule A/B

Schedule F

Schedule N

Attachment 2: Leachate Analysis

Attachment 3: HDPE Pipe Specifications

Attachment 4: Lift Station Calculations

Attachment 5: Figures

Figure 1: Site layout

- Figure 2: Details

- Figure 3: Lift Station and Details

Figure 4: Erosion Controls

cc: Joseph Benedict - Forest Preserve District of DuPage County William Beckman - Village of Hanover Park

Attachment 1 **Application for Permit or Construction Approval (WPC-PS-1)**

I:\WPMSN\PJTI\01793\04\005\L0179304005-002.DOCX



Illinois Environmental Protection Agency Permit Section, Division of Water Pollution Control P.O. Box 19276 Springfield, Illinois 62794-9276

For IEPA Use:	

Application for Permit or Construction Approval WPC-PS-1

1.	Owner Name: Forest Preserve District of DuPage County						
	Name of Project: Mallard North Landfill Leachate Connection to Village of Hanover Park Sanitary Force Main						
	Township: Bloomingdale Township County: DuPage County						
2.	Brief Description of Project:						
	The Forest Preserve District of DuPage County plans to connect the existing leachate extraction system at the closed Mallard North Landfill to an existing force main, owned and operated by the Village of Hanover Park. The existing force main is approximately 175 feet south of the landfill.						
3.	Documents Being Submitted: If the Project involves any of the items listed below, submit the corresponding schedule and check the appropriate boxes.						
	Schedule Private Sewer Connection/Extension A/B ☑ Spray Irrigation H ☐ Sewer Extension Construct Only C ☐ Septic Tanks I ☐ Sewage Treatment Works D ☐ Industrial Treatment/Pretreatment J ☐ Excess Flow Treatment E ☐ Waste Characteristics N ☑ Lift Station/Force Main F ☑ Erosion Control P ☐ Fast Track Service Connection FTP ☐ Trust Disclosure T ☐ Sludge Disposal G ☐ Permit						
	No. of Pages:						
	Specifications: Title Attachment 2 - HDPE Pipe Specifications and Standard Specifications for Water and Sewer						
	Main Construction in Illinois No. of Books/Pages:						
	Other Documents: NA						
3.1	(Please Specify) Illinois Historic Preservation Agency approval letter: Yes \(\subseteq No \(\subseteq \) forcemain, and river relocation)						
4.	Land Trust: Is the project identified in item number 1 herein, for which a permit is requested, to be constructed on land which is the subject of a trust? Yes \sum No \subseteq \text{No \subseteq}						
	If yes, Schedule T (Trust Disclosure) must be completed and item number 7.1.1 must be signed by a beneficiary, trustee or trust officer.						
5.	This is an A pplication for (Check Appropriate Line):						
	 ✓ A. Joint Construction and Operating Permit ☐ B. Authorization to Construct (See Instructions) NPDES Permit No. IL00 ☐ C. Construct Only Permit (Does Not Include Operations) ☐ D. Operate Only Permit (Does Not Include Construction) 						

6.	Certifications and Approval:						
	6.1 Certificate by Design Engineer (When required: refer to instructions) I hereby certify that I am familiar with the information contained in this application indicated above, and that to the best of my knowledge and belief such information the plans and specifications (specifications other than Standard Specifications Agency) as described above were prepared by me or under my direction.	ion is true, complete and accurate.					
	Engineer Name: Jan C. Kucher	(Seal)					
	Registration Number: 062 - 048581 (6 digits) Firm: RMT, Inc.						
	Address: 744 Heartland Trail						
	City: Madison State: WI Zip: 53717	Phone No: (608) 831-4444					
	Signature X	Date:					
	7.1 Certificate by Applicant(s) I/We hereby certify that I/we have read and thoroughly understand the conditions and requirements of this Application, and am/are authorized to sign this application in accordance with the Rules and Regulations of the Illinois Pollution Control Board. I/We hereby agree to conform with the Standard Conditions and with any other Special Conditions made part of this Permit. 7.1.1 Name of Applicant for Permit to Construct: Forest Preserve District of DuPage County						
	Address: 3S580 Naperville Road (60189-8761), PO Box 5000						
	City: Wheaton State: _ IL	Zip Code: 60189-5000					
	Signature X Da						
		one No: (630) 462-5653					
	Title: Director						
	Organization: Forest Preserve District of DuPage County						
	7.1.2 Name of Applicant for Permit to Own and Operate: Forest Preserve District of DuPage County						
	Address: 3S580 Naperville Road (60189-8761), PO Box 5000						
	City: Wheaton State: IL Z	lip Code: 60189-5000					

Date:

Phone No: <u>(630)</u> 462-5653

Title: Director

Printed Name: Joseph R. Benedict

Signature X _____

.2	Attested (Required When Applicant is a Unit of Govern	ment)				
igna	ature X	Date:				
itle:	:					
		(City Clerk, Village Clerk, Sanitary District Clerk, Etc.				
.3	Applications from non-governmental applicants which principal executive officer of at least the level of vice p					
.4	Certificate By Intermediate Sewer Owner					
11	hereby certify that (Please check one):					
	 ✓ 1. The sewers to which this project will be tributary has wastewater that will be added by this project without Act or Subtitle C. Chapter I, or ☐ 2. The Illinois Pollution Control Board, in PCB variance from Subtitle C, Chapter I to allow constructions. Name and location of sewer system to which this project was a sewer system. 	ut causing a violation of the environmental Protection datedgranted a uction of facilities that are the subject of this application				
	Sewer System Owner: Village of Hanover Park	<u> </u>				
A	Address: Public Works Facility, 2121 West Lake Street					
C	City: Hanover Park	State: IL Zip Code: 60133				
Si	Signature X	Date:				
Pi	Printed Name: William J. Beckman, P.E.	Phone No: 630-372-4271				
Ti	Title: Village Engineer					
	7.4.1 Additional Certificate By Intermediate Sewer Owner I hereby certify that (Please check one):					
	The sewers to which this project will be tributary has wastewater that will be added by this project without Act or Subtitle C. Chapter I, or	ut causing a violation of the environmental Protection				
	 Z. The Illinois Pollution Control Board, in PCB variance from Subtitle C, Chapter I to allow constr ✓ 3. Not applicable 	dated granted a granted a uction facilities that are the subject of this application.				
N	Name and location of sewer system to which this project w	ill be tributary:				
S	Sewer System Owner:					
Α	Address:					
С	City:	State: Zip Code:				

Signature X _____ Date: _____

Printed Name:	Phone No:					
Title:						
7.5 Certificate By Waste Treatment Works Owner						
I hereby certify that (Please check one):						
wastewater that will be added by this project Act or Subtitle C, Chapter I, or	ect will be tributary has adequate reserve capacity to treat the strain without causing a violation of the Environmental Protection					
2. The Illinois Pollution Control Board, in PCB Subtitle C, Chapter I to allow construction a application.	dated granted a variance from nd operation of the facilities that are the subject of this					
☐ 3. Not applicable						
I also certify that, if applicable, the industrial waste treated by the treatment works.	also certify that, if applicable, the industrial waste discharges described in the application are capable of being reated by the treatment works.					
Name of Waste Treatment Works: Village of Hanov	Name of Waste Treatment Works: Village of Hanover Park Waste Water Treatment Plant					
Waste Treatment Works Owner: Village of Hanove	er Park					
Address: Public Works Facility, 2121 West Lake S	treet					
City: Hanover Park	State: IL Zip Code: 60133					
Signature X	Date:					
Printed Name: William J. Beckman, P.E.	Phone No: 630-372-4271					
Title: Village Engineer						

Please return completed form to the following address:

Illinois Environmental Protection Agency Permit Section, Division of Water Pollution Control P.O. Box 19276 Springfield, Illinois 62794-9276

|--|

ILLINOIS ENVIRONMENTAL PROTECTION AGENCY DIVISION OF WATER POLLUTION CONTROL PERMIT SECTION

Springfield, Illinois 62794-9276

SCHEDULE A/B

ΑP	PLICATION FOR SANITARY SEWER: (please check one or both boxes as applicable) Service Connection – Schedule A 区 Publicly Owned or Regulated Extensions – Schedule B □
1.	NAME OF PROJECT: Mallard North Landfill Leachate Connection to Hanover Park Force Main
2.	TYPE OF SERVICE(S): Residential; Commercial; Light Industrial (Domestic Waste Only);
	Manufacturing ☐ ; Recreational ☐ ; Other ☒ (check all that apply)
3.	NATURE OF PROJECT: Project consists of: a sewer extension ☐ ; a sewer connection ☑ ;
	a trunk sewer ; a replacement sewer ; a relief sewer ; an interceptor sewer ;
	a new sanitary sewer (check all that apply)
4.	PROJECT LOCATION, SERVICE AREA AND POPULATION: Submit map(s) of the service area that includes the
	following:
	4.1 An 8½ X 11 inch detailed project location map or USGS map showing the project with respect to major
	roadways. In lieu of this map, a letter from the Illinois Historic Preservation Agency indicating compliance with
	the Illinois Historic Preservation Act for this project may be submitted.
	4.2 The proposed sewer layout and project location.
	Township 40N Section 7 Range 10E
	4.3 Residential and/or non-residential areas and their associated waste loads to be immediately served by the
	sewers of this project.
	4.4 Potential residential and/or non-residential areas and their associated loads must be included in the overall
	design of the sewers of this project.
5.	FACILITIES PLANNING AREA: This project is ⊠ is not □ being constructed entirely within the Facilities
	Planning Area (FPA) boundaries. Name of FPA: Village of Hanover Park
s	TYPE OF DEVELOPMENT: The following design criteria should be used in estimating the population equivalent
Ο.	(P.E.) of a residential building:
	(i .L.) of a residential building.
	Efficiency or Studio Apartment = 1 P.E. Commonly used quantities of sewage flows from miscellaneous
	1 Bedroom Apartment = 1.5 P.E type facilities are listed in Appendix B, Table No. 2 of the Illinois 2 Bedroom Apartment = 3 P.E. Recommended Standards for Sewage Works.
	3 Bedroom Apartment = 3 P.E.
	Single Family Home = 3.5 P.E. Mobile Home = 2.25 P.E.
	6.1 RESIDENTIAL BUILDINGS: Number of building(s) NA
	Number of single family dwelling building(s) NA ; Number of multiple dwelling buildings* NA ;
	Estimated total population equivalentNAP.E.
	* Please provide an itemized list for each multiple dwelling building including: Number of 1, 2 and 3 bedroom
	units; the total P.E. for the each building and the total P.E. for multiple family dwellings.

6.2	NC	N-RE	SIDEN	TIAL BUILI	DINGS: Des	scribe us	se of buildin	g(s)			
	N	ot app	olicable.								
	Pr	rincipa	al produ	ct(s) or acti	vities						
	- 1							a municipal soli ry forcemain.	d waste closed	d landfill. Le	achate and
	∟ Nu	mber	of non-ı	esidential b	ouilding(s) to	be serv	ed under th	is Permit	NA		
					is 🛛 (see s			produced i	nside the build	ling(s). If lic	quid wastes
	Est	timate	d numb	er of emplo	yees	1A	; Estimated	I number of occ	cupants (trans	ients)!	<u>NA</u> .
					valent (one pounds of su			nt is 100 gallor		per day, co	
							·	spended Solids		_	
6.3								age Flow			esian Max
0.0						-	_	BOD; P.E.			
		nnecti	ons and Dollars			the con	ditions listed opulation Eq 1 2 - 20 21 - 1 101 -	00			
"Tre	asu oloye	rer, S ee Ide	State of entification	Illinois, Er on Number	nvironmental (FEIN) appe	Protect earing o	ction Permit in the face o	4 or 6.5; certi and Inspection of the check and or any reason,	on Fund" with d submit along	the applica with this so	ant's Federal
		Any	Departrunit of land the cogrants The uranothe Include	nent, Agenocal govern st of the insor loans, fe it of local or person (e a certifie	stallation o r e deral grants government xcept for Sta	State G all of the extension or loads is NOT ate grant he bude	ne following on is paid wh s, or any col given moni ts or loans c get item or	conditions are nolly from monion mbination there les, reimbursed or federal grants the board or nd	es of the unit o eof; I or paid, eitho s or loans;	er in whole	or in part, by
					(Sign	nature fo	r Unit of Go	vernment)			
			hereby	certify that	subsections	s (b)(1),	(b)(2) and (c)(1) have beer	n met.		

6.5 A \$1,000 fee shall be required for any industrial wastewater source that does not require pretreatment of the wastewater prior to discharge to the publicly owned treatment works or publicly regulated treatment works.

7.	Standards for Sewage said criteria. If deviate	e Works", Current E	dition. This su	bmittal does	does no	t 🗵 include	s Recommended e deviations from
8.	INFILTRATION/EXFII	LTRATION LIMITS:	200	gallor	s per inch diar	neter of sewer	pipe per mile per
9.	SUMMARY OF SEWI	ERS:					
	Submit plan and profithe domestic wastewa						
	more, where non-do	mestic waste is pro					
	publicly- regulated se	<u>wer.</u>					
		Service Conn	ections	Publi	cly Owned or	Regulated Exte	ensions
Рiр	e size – inches	4					
Tot	tal Length – feet	880					
Mir	n. slope used - %	0.5					
Ma	x. slope used - %	12.6					
Mir fee	n, cover over sewers - t	2*					
Pip	e Material & Specs.	HDPE SDR 17					
Joi	nt Material & Specs.	Electro Fusion			***************************************		
To	tal Manholes	2					
	x. Distance Between	815	-				
Be Pip	dding Class for Rigid be B, or C per ASTM	NA					
Fle (IA	dding Class for exible Pipe , IB, II, or III per TM 2321-89)	III - outside of waste					
		ated in a flood plain sion of Water Resou				inois Departme nents.	nt of Natural
	9.2 Water tight manh may be flooded l	hole covers used on by surface runoff or l				elow cover or w	here the tops
10.	EROSION CONTROL Edition, distributed by deviation from said cr for Schedule P to dete	the National Resou iteria. If deviations a	rce Conservation are included, ju	on Service. The stification for s	nis submittal do	es 🔲 does	not 🗵 include

^{*} Insulation will be added if cover is less than 4 feet.

	A.	 existing combined sewer 5. propose 	ed combined sewer ed sanitary sewer ed combined sewer	
		If permitted but not constructed and operational provide permit number		
		Size and location of downstream sewer(s): Existing 16-inch-diameter force main approximately 175 feet south of the Mallard	North Landfill.	
12.		TER SUPPLY PROTECTION: The horizontal and/or vertical separation between accordance with Section 370.350 of the Illinois Recommended Standards for Sev	•	
	<u>The</u>	location of proposed and existing watermain(s) must be shown in both the plan a	nd profile views on	plan sheet(s
		each water-sewer line crossing and at all locations within 10 feet horizontal distance		sewer line.
	<u>Deta</u>	ailed drawing(s) for crossings, either typical or site-specific, shall be shown on the	plan sheet(s).	
	12.1	HORIZONTAL SEPARATION: All sewer line(s) is(are) 10 feet from water line(s]
		If no, provide justification AND describe the precautionary features against conta	amination	
		No water lines in area		
		All proposed forcemain(s) 10 feet from water line(s) YES NO N/A		
	12.2	VERTICAL SEPARATION:		
		A. The water line(s) is(are) at least 18 inches above the sewer line(s) YES	NO 🗌 . If no, co	ontinue with
		12.2.B and provide justification below as to why this is not possible and des	cribe precautionary	measures
		taken to prevent contamination.		
		B. The water line(s) is(are) above the sewer line(s) but less than 18 inches YE		
		with 12.2.C and provide justification below as to why this is not possible and	I describe precautio	nary
		measures taken to prevent contamination.	NO 🗆 If no	provido
		C. The water line(s) is(are) at least 18 inches below the sewer line(s) YES justification below as to why this is not possible and describe precautionary		•
		contamination.	meddared taken to	provent
		Justification and precautionary measures:		
		No water lines in area		
	40.0	Proximity to wells, reservoirs, and other potable water sources: YES N/A		
	12.5	, , , , , , , , , , , , , , , , , , ,	_	
		If Yes, Minimum distance feet. Describe precautionary measures	taken to avoid conta	amination:
		Location of all potable water sources shown on plan sheets. YES \(\square\) NO \(\square\)	NO KNOWN SOL	JRCES ⊠
13.	PIP	E AND MANHOLE TESTING:		
	Is in	filtration testing included in plans, specifications, or special provisions?	YES 🗌	NO 🗵
	ls e	xfiltration test included in plans, specifications, or special provisions?	YES 🗆	NO ⊠
		r testing included in plans, specifications, or special provisions?	YES 🗵	NO 🗆
		kage testing for manholes included in plans, specifications, or special provisions?	<u> </u>	NO 🗆
		The state of the s		_

11. EXISTING SEWER SYSTEM:

	Is defl	ection test included in plans, specifications, or special provisions in accordance with the Illinois Recommended
	Stand	ards for Sewage Works, Current Edition? YES 🔲 NO 🗵 N/A 🗌
15.	MISCI	ELLANEOUS REQUIREMENTS:
		ollowing requirements should be included on the plan sheets where so indicated. For items where this is not ied, the requirements may be on the plan sheets, in the specifications, or in the special provisions:
	15.1	Standard Specifications for Water and Sewer Main Construction in Illinois, Current Edition, govern the construction of this project. YES X NO . If no, please provide specifications.
	15.2	Pipe and joint ASTM/AWWA designation included on plan sheets. YES ☒ NO ☐
	15.3	All flexible gravity sewer pipe installed in accordance with ASTM D2321-89; embedment materials for bedding,
		haunching, and initial backfill to at least 6 inches over the top of the pipe with Class IA or IB or II or III;
		processed material produced for highway construction used in the project classified according to particle size, shape, and gradation in accordance with ASTM D2321-89, Section 9 and Table 1. YES X NO X N/A X
	15.4	All rigid gravity sewer pipe installed in accordance with ASTM C12 and bedding material Class A, B, or C.
		YES NO N/A 🗵
	15.5	Pickholes in all manholes likely to be flooded not larger than 1 inch in diameter and of the concealed type.
		YES X NO N/A X
	15.6	All manholes numbered. YES ☒ NO ☐ N/A ☐
	15.7	Match lines shown on all plan sheets. YES ☐ NO ☐ N/A ☒

14. FLEXIBLE PIPE TESTING:

This Agency is authorized to require this information under Illinois Revised Statutes, 1979, Chapter 111 1/2, Section 1039. Disclosure of this information is required under that Section. Failure to do so may prevent this form from being processed and could result in your application being denied. This form has been approved by the Forms Management Center.

Illinois Environmental Protection Agency

Division of Water Pollution Control, Permit Section Post Office Box 19276 Springfield, Illinois 62794-9276

Schedule F - Sewer System Lift Station / Force Main

1.	Name	of Project:	Mallard N	lorth Landfill Le	achate (Connect	tion to Vi	llage of	Hanov	/er Pa <u>rk Sa</u>	nitary Foi	ce Main	-
2.	Desigi	n Population: Area to	be serve	d NA		acres.	Popula	ation to I	be sen	ved	NA	P.E.,	
3.	Design	ı Flows:											
		Design A	verage Fl	ow <u>14</u>		gpm.	Design	Maximu	ım Flo	w4	0	gpm.	
4.	O	ation will serve only separate se omestic waste	ewers	☐Only combin ⊠Industrial wa							vers		
5.		ation is desig ly the populati		rve: ed above □ □ A	ın anticip	pated ad	lditional v	waste co	ontribu	tion of	NA		P.E
6.		of Force Mair		4									
	Pipe	material spec	cifications	HDPE			Joint	t specific	cations	s <u>Fusion</u>			
				d at high points? rovided at low p] No						
7.	_	n Head (Total	•	•			772.0						
	A)	Static Hea		charge Elevatio	_				-				
		sting Force in Tie-in = 4 5.1	Lov 7 ft	v Water Elevation	on: _		765.5						
	Pre	ssure ~19.8 p	sig Sta	tic Head	_		55.0		Feet				
	B)	Pipe frict	ion loss:				5.0		Feet	at "C" =	1.0	_	
	C)	Minor Los	sses (Val	ves, etc.)	_		1.0		Feet	at "C" = 10	0		
		Total Dyn	namic Hea	ad (A + B + C)		<u> </u>	61		Feet				
		Maximum	1 Suction	Lift (if applicab	le) _		NA		Feet				
8.	Pump	6											
	umber of umps		Туре о	f Pump			/ per mp	at TD (Fee		H.P. of Each Pump		ass 3" oheres	
	2	Grundfos Sul	bmersible	1 hp, single ph	ase	4	10	61		1.03	□Y€	es ⊠No	
											□Y€	es 🗌 No	
											□Y€	es 🗆 No	
а.	Rated C	apacity of Lift	Station _	40	gpr	n at	61	f	eet of	TDH.			
b.	Pumping	g Capacity with	h Largest	Unit Out of Serv	vice	0		gpm at			feet of T	DH.	
C.	Are all p	umps with pos	sitive sucti	on head and/or	self prir	ming?				⊠Y	′es □N	0	
d.	Have pr	ovisions been	made to d	detect shaft sea	l failure	or poten	itial shaft	t seal fai	ilure?	□Y	′es ⊠N	0	

Schedule F - Sewer System Lift Station / Force Main Page 2

a. Discharge Pipe b. Suction Line (if applicable)
a. Effective capacity (volume between pumps off and pumps on switches) = 633 gallons b. Detention time at design flow = 16 minutes c. Are there provisions for pump removal?
b. Detention time at design flow = 16 minutes c. Are there provisions for pump removal?
the continuous with at least 12 complete air changes per hour? Continuous with at least 30 complete air changes per hour? Continuous with at least 30 complete air changes per hour? Continuous with at least 30 complete air changes per hour? Continuous with at least 30 complete air changes per hour? Yes No No No No No No No N
a. Have buoyancy calculations been submitted? b. Depth of groundwater table: 0 feet below the ground surface. 12. Accessability a. Is the pump station accessible by an all weather road? 13. Ventilation a. Wet Well: Continuous with at least 12 complete air changes per hour? Intermittent with at least 30 complete air changes per hour? Continuous with at least 6 complete air changes per hour? Continuous with at least 6 complete air changes per hour? Continuous with at least 6 complete air changes per hour? Yes No No N/A Intermittent with at least 30 complete air changes per hour? Yes No No N/A
a. Have buoyancy calculations been submitted? b. Depth of groundwater table: 0 feet below the ground surface. 12. Accessability a. Is the pump station accessible by an all weather road? 13. Ventilation a. Wet Well: Continuous with at least 12 complete air changes per hour? Intermittent with at least 30 complete air changes per hour? Continuous with at least 6 complete air changes per hour? Continuous with at least 6 complete air changes per hour? Continuous with at least 6 complete air changes per hour? Yes No No N/A Intermittent with at least 30 complete air changes per hour? Yes No No N/A
12. Accessability a. Is the pump station accessible by an all weather road? 13. Ventilation a. Wet Well: Continuous with at least 12 complete air changes per hour? Intermittent with at least 30 complete air changes per hour? Dry Well (if applicable): Continuous with at least 6 complete air changes per hour? Intermittent with at least 30 complete air changes per hour? Yes No NA
a. Is the pump station accessible by an all weather road? 13. Ventilation a. Wet Well: Continuous with at least 12 complete air changes per hour? Intermittent with at least 30 complete air changes per hour? Dry Well (if applicable): Continuous with at least 6 complete air changes per hour? Intermittent with at least 30 complete air changes per hour? Yes No ⊠N/A Intermittent with at least 30 complete air changes per hour? Yes No ⊠N/A
13. Ventilation a. Wet Well: Continuous with at least 12 complete air changes per hour? Intermittent with at least 30 complete air changes per hour? Dry Well (if applicable): Continuous with at least 6 complete air changes per hour? Intermittent with at least 30 complete air changes per hour? Yes □No ☑N/A Intermittent with at least 30 complete air changes per hour? □Yes □No ☑N/A
a. Wet Well: Continuous with at least 12 complete air changes per hour? Intermittent with at least 30 complete air changes per hour? Dry Well (if applicable): Continuous with at least 6 complete air changes per hour? Intermittent with at least 30 complete air changes per hour? Yes □No ☑N/A N/A
Continuous with at least 12 complete air changes per hour? Intermittent with at least 30 complete air changes per hour? Dry Well (if applicable): Continuous with at least 6 complete air changes per hour? Intermittent with at least 30 complete air changes per hour? Yes No NA N/A
Intermittent with at least 30 complete air changes per hour? b. Dry Well (if applicable): Continuous with at least 6 complete air changes per hour? Intermittent with at least 30 complete air changes per hour? Yes No N/A N/A
Continuous with at least 6 complete air changes per hour? ☐ Yes ☐ No ☒ N/A Intermittent with at least 30 complete air changes per hour? ☐ Yes ☐ No ☒ N/A
Intermittent with at least 30 complete air changes per hour? ☐ Yes ☐ No ☒ N/A
c. Is portable ventilation equipment available for use at all times?
14. Emergency Operations
a. In case of power failure, is an alternate power supply available? ☐Yes ☒No If yes, please describe the source:
b. Is a portable pump, with adequate pumping capacity, available for use at all times? ☐ Yes ☒No
d. Length of time between a power failure and commencement of pumping by emergency equipment NA
e. Estimated time interval before damage or sewer backup will occur <u>NA</u> .
f. Type of alarm system proposed: ⊠Telemetering System ☐ Audio-Visual with self contained power
g. Are personnel available at all times to operate emergency equipment? ☐Yes ☒No
15. Flow Measurement
a. Type of flow measurement provided: ⊠Flow meter □ Elapsed time meters □tTR
16. Compliance with Illinois Recommended Standards for Sewage Works
a. Can the pump station remain operational during the 25 year flood?
c. When applicable, will electrical systems and components comply with NEC
requirements for Class I, Group D, Division I locations? d. Have provisions been made to automatically alternate the pumps? □Yes ☒No
e. Is the motor control center located outside and protected by a conduit seal? In the motor be electronically disconnected without disturbing the seal? In the motor be electronically disconnected without disturbing the seal? In the motor be electronically disconnected without disturbing the seal?

This Agency is authorized to require this information under Illinois Revised Statutes, 1979, Chapter 1112, Section 1039. Disclosure of this information is required under that Section. Failure to do so may prevent this form from being processed and could result in your application being denied. This form has been approved by the Forms Management Center

This Agency is authorized to require this information under Illinois Revised Statutes, 1979, Chapter 111 1/2, Section 1039. Disclosure of this information is required under that section. Failure to do so may prevent this form from being processed and could result in your application being denied.

For IEPA Use:	
LOG#	
DATE RECEIVED:	

ILLINOIS ENVIRONMENTAL PROTECTION AGENCY DIVISION OF WATER POLLUTION CONTROL PERMIT SECTION Springfield, Illinois 62794-9276

SCHEDULE N WASTE CHARACTERISTICS

1.	Name of Project Mallard North	th Landfill Leachate	Connection to	Village of	Hanover Park Sa	nitary Force	emain
2.	FLOW DATA	EXISTING		PROPOSED-DESIGN			
	2.1 Average Flow (gpd)	·			20,000		
	2.2 Maximum Daily Flow (gpd)	·		60,000	17771111	
	2.3 <u>TEMPERATURE</u> Appro	ximately 70-80°F (leachate from	closed land	fill)		
	Tìme of Year	Avg. Intake // Temp. F	Avg. Effluent Temp. F	Max. Int		Effluent mp F.	Max. Temp. Outside Mixing Zone F
	SUMMER						
	WINTER						
	 2.4 Minimum 7-day, 10-year fl 2.5 Dilution Ratio: N/A 2.6 Stream flow rate at time of 				IGD.		
3.	CHEMICAL CONSTITUENT E	xisting Permitted Co	nditions 🔲 💢 ; E	Existing conc	ditions 🗵 💢 ; Propo	sed Permitt	ted Conditions □
	Type of sample: ⊠ grab (tim	ne of collection	13:30);	□ composi	ite (Number of sam	iples per da	y)
	(see instructions for analyses	required) 5/28/201	0; see attache	d analysis			
	CONSTITUENT	RAW WASTE (mg/l)	TREATED E Avg. (mg/		UPSTREAM (mg/l)	DOWNST	REAM SAMPLES (mg/l)
	Ammonia Nitrogen (as N)						
	Arsenic (total)						
	Barium		***************************************				
	Boron		***************************************				
	BOD ₅						
	Cadmium						
	Carbon Chloroform Extract						
	Chloride						
	Chromium (total hexavalent)						
	Chromium (total trivalent)				***************************************		

CONSTITUENT	RAW WASTE (mg/l)	TREATED EFFLUENT Avg. (mg/l) Max.	UPSTREAM (mg/l)	DOWNSTREAM SAMPLES (mg/l)
Copper				
Cyanide (total)				
Cyanide (readily released @ 150° F & pH 4.5)				
Dissolved Oxygen				
Fecal Coliform				
Fluoride				
Hardness (as Ca CO ₃)				
Iron (total)				
Lead				
Manganese				
MBAS				
Mercury				
Nickel				
Nitrates (as N)				
Oil & Grease (hexane solubles or equivalent)				
Organic Nitrogen (as N)				
рН				
Phenols				
Phosphorous (as P)				
Radioactivity				
Selenium				
Silver				
Sulfate				
Suspended Solids				
Total Dissolved Solids				
Zinc				
Others				
		1	<u> </u>	I .

Attachment 2

Leachate Analysis



December 30, 2010

Corporate Office: 360 S. Main Place, Carol Stream, IL 60188-2404 630,462.2600 • Fax 630.653.2988

Mr. Drew Bergenthal Forest Preserve District of Du Page County 3 S. 580 Naperville Road Wheaton, IL 60189-8761

Re: L-61,102

Mallard North Landfill

Leachate Sampling Well EWL2 2nd 2010 Semi-Annual Event

Fox River Water Reclamation District

Dear Mr. Bergenthal:

Testing Service Corporation has completed the 2nd 2010 Semi-Annual Leachate Sampling of well EWL2 at Mallard North Landfill. A new disposable sample bailer was used to collect the leachate. The leachate was transferred to appropriate sample containers, placed in an ice filled chest and transported to First Environmental Laboratories, Inc., in Naperville, Illinois. Analysis was performed for the <u>semi-annual parameters</u>, as prescribed by the Fox River Water Reclamation District. Copies of the Analytical Report and Chain-of-Custody are enclosed.

It has been a pleasure to assist you with this work. Please call me at (630) 784-4005 if there are any questions or when we can be of further service.

Respectfully,

TESTING SERVICE CORPORATION

David L. Hurst

Environmental Department Manager

Enc. Analytical Report

Chain of Custody



1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

December 30, 2010

Mr. Dave Hurst TESTING SERVICE CORP. 360 So. Main Place

Carol Stream, IL 60188

Project ID: 61.102

First Environmental File ID: 10-5666 Date Received: December 23, 2010

Dear Mr. Dave Hurst:

The above referenced project was analyzed as directed on the enclosed chain of custody record.

All Quality Control criteria as outlined in the methods and current IL ELAP/NELAP have been met unless otherwise noted. QA/QC documentation and raw data will remain on file for future reference. Our accreditation number is 100292 and our current certificate is number 002468; effective 02/23/2010 through 02/28/2011.

I thank you for the opportunity to be of service to you and look forward to working with you again in the future. Should you have any questions regarding any of the enclosed analytical data or need additional information, please contact me at (630) 778-1200 or stan@firstenv.com.

Sincerely,

Stan Zaworski Project Manager



1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

Case Narrative

TESTING SERVICE CORP.

Project ID:

61.102

First Environmental File ID: 10-5666 Date Received: December 23, 2010

Flag	Description	Flag	Description
<	Analyte not detected at or above the reporting limit.	Ĭ ,÷	LCS recovery outside control limits; high bias.
ß	Analyte detected in associated method blank.	[LCS recovery outside control limits; law bias.
C	Identification confirmed by GC/MS.	M	MS recovery outside control limits; LCS acceptable.
D	Surrogates diluted out; recovery not available.	Mr	MS recovery outside control limits high bias; LCS acceptable.
E	Estimated result; concentration exceeds calibration range.	M-	MS recovery outside control limits fow bias; LCS acceptable.
1-	Field measurement.	N	Analyte is not part of our NELAC accreditation.
		ND	Analyte was not detected using a library search routine; No calibration standard was analyzed.
G	Surrogate recovery outside control limits; matrix effect.	þ	Chemical preservation pH adjusted in lab.
H	Analysis or extraction holding time exceeded.	Q	The analyte was determined by a GC/MS database search.
J	Estimated result; concentration is less than calib range.	S	Analyte was sub-contracted to another laboratory for analysis.
K	RPD outside control limits.	Ŧ	Sample temperature upon receipt exceeded 0-6°C
RL	Routine Reporting Limit (Lowest amount that can be detected when routine weights/volumes are used without dilution.)	W	Reporting limit elevated due to sample matrix,

All quality control criteria, as outlined in the methods, have been met except as noted below or on the following analytical report.

Sample Batch Comments:

Time of sample collection was not provided.



First Environmental Laboratories, Inc.

IL ELAP / NELAC Accreditation # 100292

1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

Analytical Report

Client: TESTING SERVICE CORP.

10-5666-001

Date Collected: 12/23/10

Project ID: 61.102

Sample No:

Time Collected:

Sample ID: EWL-2, 4Q2010

Date Received: 12/23/10

Date Reported: 12/30/10

Analyte		Result	R.L.	Units	Flags
Volatile Organic Compounds Analysis Date: 12/28/10	Method: 624			······································	
Acrolein		< 100	100	սջ/Լ	
Acry)oniteile		< 100	100	ug/L	
Benzene		7.3	5.0	ug/L	
Bromodichloromethane		< 1.0	1.0	ug/L	,
Bromoform		< 1.0	10	ug/L	
Bromomethane		< 5.0	5.0	ug/L	
Carbon disulfide		< 5.0	5.0	ug/L	
Carbon tetrachioride		< 5.0	5.0	ug/L	
Chlorobenzene		40.3	5.0	ug/L	
Chlorodibromomethane		< 1.0	1.0	ug/L	
Chloroothane		< 10.0	10.0	ug/L	
2-Chloroethyl vinyl ether		< 10.0	10.0	ug/L	
Chloroform		< 1.0	1.0	ug/L	
Chloromethane		< 10.0	10.0	ug/L	
1,2-Dichlorobenzene		< 5.0	5.0	ug/L	
1,3-Dichlorobenzene		< 5.0	5.0	ug/L	
1,4-Dichlorobenzene		10.4	5.0	ug/L	
I, I-Dichloroethane		< 5.0	5.0	ug/L	
1,2-Dichloroethane		< 5.0	5.0	ug/L	
1,1-Dichloroethene		< 5.0	5.0	ug/L	
cis-1,2-Dichlorocthene		< 1.0	1.0	u <i>g</i> /L	
trans-1,2-Dichloroothene		< 1.0	1.0	ug/L	
1,2-Dichforopropane		< 5.0	5.0	ug/L	
cis-1,3-Dichloropropene		< 5.0	5.0	ug/L	
trans-1,3-Dichloropropene		< 5.0	5.0	ug/L	
Ethylbenzene		< 5.0	5.0	нд/Д	
Methylene chloride		< 5.0	5.0	ug/L	
1,1,2,2-Tetrachloroethane		< 5.0	50	ug/L	
Tetrachloroethene		< 5.0	5.0	ug/1.	
Toluene		< 5.0	5.0	ug/l_	
1,1,1-Trichforoethane		< 5.0	5.0	ug/L	
1,1,2-Trichloroethane		< 5.0	5.0	ug/L	
Trichloroethene		< 5.0	5.0	ug/L	
Vinyl chloride		< 2.0	2,0	ug/L	



1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

Analytical Report

Client: TESTING SERVICE CORP. Date Collected: 12/23/10

Project ID: 61.102 Time Collected:

Sample ID:	EWL-2, 4Q2010	Date Received:	12/23/10
Sample No:	10-5666-001	Date Reported:	12/30/10

Analyte		Result	R.L.	Units	Flags
Ammonia (as N) Analysis Date: 12/28/10	Method: 350.1R2.	0			
Ammonia (as N)		210	0.10	mg/l_	
COD Analysis Date: 12/28/10	Method: 5220D				•
COD		306	10	mg/L	
Cyanide, Total Analysis Date: 12/29/10	Method: 335.4R1.				
Cyanide, Total		0.005	0.005	mg/L	
Oil & Grease Analysis Date: 12/28/10	Method: 1664A				
Oil & Grease		2	1	mg/L	
pH @ 25°C Analysis Date: 12/27/10 11:15	Method: 4500II+,	В			
рН @ 25°С		7.53		Units	
Phosphorus (as P) Analysis Date: 12/29/10	Method: 4500P,B,	E	· · · · · · · · · · · · · · · · · · ·		
Phosphorus (as P)		< 0.01	0.01	mg/L	
Phenols Analysis Date: 12/30/10	Method: 420.4R1.	0			
Phenols		0.011	0.010	mg/L	
Total Metals Analysis Date: 12/29/10	Method: 200.7R4.	4	Preparation Preparation D		
Arsenic	•	< 0.002	0,002	${\sf mg/L}$	
Barium		0.492	0.001	mg/L	
Cadmium	•	< 0.001	0.001	mg/L	
Chromium		0.004	0.001	mg/L	
Copper	•	< 0.001	0.001	mg/L	
Iron		314	0.01	ing/L	
Lead		0,003	0.002	mg/L	
Manganese		0.232	0.001	mg/L	
Nickel		0.025	0.001	mg/L	
Zine		0.023	0.005	mg/L	



Environmental Laboratories, Inc.

IL ELAP / NELAC Accreditation # 100292

1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

Analytical Report

Client: TESTING SERVICE CORP. Date Collected: 12/23/10

Time Collected:

Project ID: 61.102 Sample ID:

Sample No:

EWL-2, 4Q2010 10-5666-001

Date Received: 12/23/10 Date Reported:

12/30/10

Analyte	Result	R.L.	Units	Flags
Total Metals Analysis Date: 12/29/10	Method: 245.1R3.0			
Mercury	< 0.0005	0.0005	mg/L	



First Environmental Laboratories, Inc.

IL ELAP / NELAC Accreditation # 100292

1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

Analytical Report

TESTING SERVICE CORP. Client:

Date Collected:

Project ID:

61.102

Time Collected:

Date Received: Date Reported:

12/23/10 12/30/10

Sample ID:	Trip Blank
Sample No:	10-5666-002

Analyte		Result	R.L.	Units	Flags
Volatile Organic Compounds Analysis Date: 12/27/10	Method: 624				
Acrolein		< 100	100	ug/L	
Acrylonitrile		< 100	100	ug/L	
Benzene		< 5.0	5.0	ug/L	
Bromodichloromethane		< 1.0	1.0	ug/L	
Bromoform		< 1.0	1.0	ug/L	
Bromomethane		< 5.0	5.0	ug/L	
Carbon disulfide		< 5.0	5.0	ug/L	
Carbon tetrachloride		< 5.0	5.0	ug/L	
Chlorobenzene		< 5.0	5.0	ug/L	
Chlorodibromomethane		< 1.0	1.0	ug/L	
Chloroethane		< 10.0	10.0	ug/L	
2-Chloroethyl vinyl ether		< 10.0	10.0	ug/L	
Chloroform		< 1.0	1.0	ug/L	
Chloromethane		< 10.0	0.01	ug/L	
1,2-Dichlorobenzenc		< 5.0	5.0	ug/L	
1,3-Dichlorobenzene		< 5.0	5.0	ug/L	
1,4-Dichlorobenzene		< 5.0	5.0	ug/L	
1,1-Dichloroethane		< 5.0	5.0	ug/L	
1,2-Dichloroethane		< 5.0	5.0	ug/L	
1,1-Dichloroethene		< 5.0	5.0	ug/L	
cis-1,2-Dichloroethene		0.1 >	1.0	ug/L	
trans-1,2-Dichloroethene		< 1.0	1.0	ug/L	
1,2-Dichloropropane		< 5.0	5.0	ug/L	
cis-1.3-Dichloropropene		< 5.0	5.0	ug/L	
trans-1,3-Dichloropropene		< 5.0	5.0	ug/L	
Ethylbenzen e		< 5.0	5.0	ug/L	
Methylene chloride		< 5.0	5.0	ug/L	
1,1,2,2-Tetrachloroethane		< 5.0	5.0	ug/L	
Tetrachloroethene		< 5.0	5.0	ug/L	
Toluene		< 5.0	5.0	ug/L	
1,1,1-Trichloroethane		< 5.0	5.0	ug/L	
1,1,2-Trichloroethane		< 5.0	5.0	ug/L	
Trichloroethene		< 5.0	5.0	ug/L	
Vinyl chloride		< 2.0	2.0	ug/L	



First	HAIN OF CUSTODY RECORD	- 11115 TO 1000 of 000
Environmental	(4	621 D. Care 1 - 185
Laboratories, Inc.	Company Name: 77	-NVOICE TO Page_of_pgs
	Company Name. 75	State: FL Zip: 60187 832988 e-mail: Attent @TSCLONG. Corr Via: Fax C-mail
First Environmental Laboratories	Street Address: 360 Sy // (4-)	IN FLACE
1600 Shore Road, Suite D	City: Gran STREAM	State: L Zip: 6018>
Naperville, Illinois 60563 Phone: (630) 778-1200 • Fax: (630) 778-1233	Phone: 6304622600 Fax: 6306	332988 e-mail: Affects @ TSCLORE COM
E-mail: firstinfo@firstenv.com	Send Report To: Diffuns	Via: Fax e-mail
IEPA Certification #100292	Sampled By: Deffunction	
	Analyses	
Project I.D.: 6/102		7 / / /
P.O. #.:		′ / / /
P.O. #.:	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
		/ / /
Matrix Codes: S = Soil W = Water O = Other		/ /
Date/Time Taken Sample Description Mat	trix	Comments Lab I.D.
		10-5666-001
12/23/10 EWL-2, 40,2010 U		042
7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7		
FOR LAB USE ONLY:		
Cooler Temperature: 0.1-6°C Yes YNo°C Sample Re	efrigerated: Yes No_ Containers Received Pres	erved: Tyes : No
Received within 6 hrs. of collection: Refrigerate	or Temperature:°C	
	s Frozen: Yes No Need to meet: JL. TACO emperature: °C	IN. RISC 📙
Notes and Special Instructions:	simperature	
A TOTAL BITCH DEPOSITE THE SECTION		
-1000000000000000000000000000000000000	1/2/ 10/20	
Relinquished By At Date/Time	1/23/10 19/20 Received By: Min Q. Hel	Date/Time 12/23/10 10:20
Relinquished By: Date/Time	Received By:	Date/Time

Rev. 9/08

TSC # L - 61,102 Mallard North Landfill- Leachate Sampling and Analysis

Semi-Annual Leachate Analysis Parameters
For both semi-annual sampling events:
Cadmium 🗸
Chromium /
Copper /
Cyanide 🗸
Lead 🗸
Mercury ✓
Nickel /
Zinc \(\)
Ammonia Nitrogen (as N)
Arsenic ✓
Barium 🗸
C.O.D. ✓
Iron ✓
Fats, Oil and Grease
Manganese / Painty/out
pH 1
Phenol I 2 1/2/47/12 PARTY POR WARE
Phosphorous V AND V
Fats, Oil and Grease / Manganese / pH / Phenol J Phosphorous / Phosphorous / AND Word 7142 PARTION POR WASTE WATER Sampled annually for: DSEPA Priority Pollutants for Wastewater

LOST LCDD.

Total Pac RD*
Total Pec RD*

Total HpCDD

OCDD*

*Using USEPA Method 8280



1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

March 12, 2010

Mr. Dave Hurst TESTING SERVICE CORP. 360 So. Main Place Carol Stream, IL 60188

Project ID: 53152

First Environmental File ID: 10-0774 Date Received: March 05, 2010

Dear Mr. Dave Hurst:

The above referenced project was analyzed as directed on the enclosed chain of custody record.

All Quality Control criteria as outlined in the methods and current IL ELAP/NELAP have been met unless otherwise noted. QA/QC documentation and raw data will remain on file for future reference. Our accreditation number is 100292 and our current certificate is number 002205; effective 02/06/09 through 02/28/10.

I thank you for the opportunity to be of service to you and look forward to working with you again in the future. Should you have any questions regarding any of the enclosed analytical data or need additional information, please contact me at (630) 778-1200 or stan@firstenv.com.

Sincerely

Stan Zaworski Project Manager



1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

Case Narrative

TESTING SERVICE CORP.

Project ID: 53152

First Environmental File ID: 10-0774
Date Received: March 05, 2010

Flag	Description	Flag	Description
<	Analyte not detected at or above the reporting limit.	La ,	LCS recovery outside control limits; high bias.
В	Analyte detected in associated method blank,	L-	LCS recovery outside control limits; low bias.
· c ·	Identification confirmed by GC/MS.	M	MS recovery outside control limits; LCS acceptable,
D	Surrogates diluted out; recovery not available,	M+	MS recovery outside control limits high bias; LCS acceptable.
E	Estimated result; concentration exceeds calibration range.	М	MS recovery outside control limits low bias; LCS acceptable.
F	Field measurement.	N	Analyte is not part of our NELAC accreditation.
	, , , , , , , , , , , , , , , , , , ,	מא	Analyte was not detected using a library search routine; No calibration standard was analyzed.
G	Surrogate recovery outside control limits; matrix effect.	P	Chemical preservation pH adjusted in lab.
Н	Analysis or extraction holding time exceeded,	Q	The analyte was determined by a GC/MS database search.
J,	Estimated result; concentration is less than calib range.	S	Analyle was sub-contracted to another laboratory for analysis.
Κ	RPD outside control limits.	Υ.	Sample temperature upon receipt exceeded 0-6°C
RL	Routine Reporting Limit (Lowest amount that can be detected when routine weights/volumes are used without dilution.)	W	Reporting limit elevated due to sample matrix.

All quality control criteria, as outlined in the methods, have been met except as noted below or on the following analytical report.

Sample Batch Comments:

Sample acceptance criteria were met.



1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

Analytical Report

Client: TESTING SERVICE CORP.

Project ID: 53152

Sample ID: EWL-2; JQ 2010

Sample No: 10-0774-001 Date Collected: 03/05/10

Time Collected: 8:15

Date Received: 03/05/10

Date Reported: 03/12/10

Analyte		Result	R.L.	Units	Flags
Ammonia (as N) Analysis Date: 03/11/10	Method: 350.11	R2. 0	_		
Ammonia (as N)		94.8	0.10	mg/L	
COD Analysis Date: 03/08/10	Method: 5220D				
COD		147	10	mg/L	
Cyanide, Total Analysis Date: 03/12/10	Method: 4500C	·	0.005	a 11	
Cyanide, Total		0.006	0,005	mg/IL	
Oil & Grease Analysis Date: 03/08/10	Method: 1664A			a.	
Oil & Grease		< I	1	mg/L	
p H @ 25°C Analysis Date: 03/05/10 16:00	Method: 4500E	I+,Ɓ			
pH @ 25°C		7.06		Units	···
Phenols Analysis Date: 03/11/10	Method: 420.41	R1.0			
Phenols		0.019	0.010	mg/L	
Chromium, Hexavalent Analysis Date: 03/11/10 15:00	Method: 3500C	Cr,B	7111111	anna anna anna anna anna anna anna ann	
Chromium, Hexavalent		< 0.050	0.05	mg/L	
Chromium, trivalent Analysis Date: 03/12/10	Method: CALC	2			THE CANAL COLUMN
Chromium, Trivalent		< 0.005	0.005	mg/L	
Chloride Analysis Date: 03/12/10	Method: 45000	CI, E		···	
Chlorid e		530	5	mg/L	
Total Metals Analysis Date: 03/12/10	Method: 6020A	<u> </u>		Method 301 Date: 03/09/10	
Arsenic		< 0.002	0.002	mg/L	
Barium		0.346	0.001	mg/L	
Boron		1.42	10.0	mg/L	
Cadmium		< 0.001	0.001	mg/L	
Chromium		< 0.001	0.001	mg/L	
Copper		0.003	0,001	mg/L	



Date Collected: 03/05/10

1600 Shore Road • Naperville, Illinois 60S63 • Phone (630) 778-1200 • Fax (630) 778-1233

Analytical Report

Client: TESTING SERVICE CORP.
Project 1D: 53152


53152 Time Collected: 8:15

Sample ID: EWL-2; 1Q 2010 Date Received: 03/05/10

Sample No: 10-0774-001 Date Reported: 03/12/10

Analyte		Result	R.L.	Units	Flags
Total Metals Analysis Date: 03/12/10	Method: 6020A Preparation Method 3010A Preparation Date: 03/09/10				
Iron		3.11	0.01	mg/L	
Lead		< 0.002	0.002	mg/L	
Manganese		0.343	0.001	mg/L	
Nickel		0.021	0.001	mg/L	
Sølenium		< 0.002	0.002	mg/L	
Silver		< 0.001	0.001	mg/L	
Zine		0.006	0.005	mg/L	
Total Metals Analysis Date: 03/10/10	Method: 7470A		A CONTRACTOR OF THE CONTRACTOR		
Mercury		< 0.0005	0.0005	mg/L	
Sulfate Analysis Date: 03/10/10	Method: 4500S0	4,E	OCCOURT COURT OF THE TOP STORES & THE CHARLES AND	umand Var F Reffer Valley franch and a committee of the c	//////////ddia:! (ht bills a.a.a (a.a.d
Sulfate		36	15	mg/L	
BOD, 5 Day Analysis Date: 03/05/10 15:00	Method: 5210B	***************************************			
BOD, 5 Day		19	1	mg/L	
Total Dissolved Solids Analysis Date: 03/09/10	Method: 2540C	agatamang chi di dinastra da ratura da di			
Total Dissolved Solids		1,890	10	mg/L	
Total Suspended Solids Analysis Date: 03/08/10	Method: 2540D		AND THE PARTY OF T		
Total Suspended Solids		39	1	mg/L	

CHAIN OF CUSTODY RECORD



First Environmental Laboratories

1600 Shore Road, Suite D

	Company Name:	<u> </u>		
INVILE DAR	Street Address:	3.60 S. 111AIN	PLA LE	
I TO DIME	City: (2/2	FROL STRAM	FL 6018) State: 2	IL Zip. 60188
Doen Beereroup	Phone:	Fax:	e-mail:	
The second of the second	Send Report To:	DAVE. Lynne 57	Via: Fax []	t-mail
har	Sampled By:	JAVE Huns		Andread Andreas
		Y A Analyses		

Naperville, Illinois 60563	Cr. Di const	Phone:	₽ax:	e-mail:	
Phone: (630) 778-1200 • Fax: (630) 778-1233 E-mail: firstinfo@firstenv.com	Dura Bestand	Send Report To:	DAVE HyreST	Via: Fax []	t-mail
IEPA Certification #100292	har.	Sampled By:	JAVE HAMPS		
<u> </u>			X Amalyses		
Project I.D.: 53/5-2		of King Say	Analyses	/ / / / /	**************************************
	HPHPHPHPHHHHHHHHHHHHHHHHHHHHHH	/.\	Ÿ,♥,0/ / /		!
P.O. #.:		/ ₂ 2			
		/ \sightarrow \(\sightarrow \)			
manual trape		N. O. O.	AND		
Matrix Codes: S = Soil W = Water O =	- Other	1.4			
Date/Time Taken Sample Descr				Comments	Lab I.D.
3-5-10, 8'5 EWLZ -10					10-0274-001
					A management
		<u> </u>			
	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~				
The state of the s					
FOR LAB USE ONLY.		\/			
Cooler Temperature: 0.1-6°C Yes_No	°C Sample Refrig			rved: []Yes []No	
Received within 6 hrs. of collection: loe Present: Yes No	Refrigerator T 5035 Viale Fo	emperature: ozen: Yes No	PC Need to meet: IL. TACO	☐ IN, RISC ☐	
TOP STORY TO SEE THE STORY TO SEE THE	Proezer Temp	erature:*c	1,000		
Notes and Special Instructions:	******	~~~~			
	······································				
					1 1
1) 2/12	11/	11 11 12 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1/1		7/05/1/45
Relinquished By:	Date/Time}		leceived By:	Date/Time	1111/0/0
Relinquished By:	Date/Time	R	eceived By:	Date/Time	
Rev. wa					

Page___of__pgs

# TSC # L - 53,152

Mallard North Landfill Leachate Sampling and Analysis

```
Quarterly Leachate Analysis Parameters
Each Quarter:
Arsenic -
Barium -
Boron -
Cadmium -
Chloride --
Chromium (hexavalent) 1
Chromium (trivalent) +
Copper -
Cyanide +
Iron (total) -
Lead
Manganese -
Mercury +
Nickel -
plil+
Phenols+
Selenium -
Silver -
Sulfate +
Zinc -
BOD5+
COD +
Oil & Grease +
Ammonia (as N) +
Total Dissolved Solids +
Total Suspended Solids *
```

### Semi-Annual:

Organic Toxic Pollutants (as defined in 40 CFR 122)

- -Volatiles
- -Acid Compounds
- -Base/Neutrals
- -Pesticides

Note: Test methods as described in 40 CFR 136 shall be utilized for analysis.

1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-I200 • Fax (630) 778-1233

June 28, 2010

Mr. Dave Hurst
TESTING SERVICE CORP.
360 So. Main Place
Carol Stream, IL 60188

Project ID: 61102

First Environmental File ID: 10-2115

Date Received: May 28, 2010

Dear Mr. Dave Hurst:

The above referenced project was analyzed as directed on the enclosed chain of custody record.

All Quality Control criteria as outlined in the methods and current IL ELAP/NELAP have been met unless otherwise noted. QA/QC documentation and raw data will remain on file for future reference. Our accreditation number is 100292 and our current certificate is number 002468: effective 02/23/2010 through 02/28/2011.

I thank you for the opportunity to be of service to you and look forward to working with you again in the future. Should you have any questions regarding any of the enclosed analytical data or need additional information, please contact me at (630) 778-1200 or neal@firstenv.com.

Sincerely,

Neal Cleghorn Project Manager

1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

#### Case Narrative

#### TESTING SERVICE CORP.

Project ID:

61102

First Environmental File ID: 10-2115

Date Received:

May 28, 2010

Flag	Description	Fing	Description
<	Analyte not detected at or above the reporting limit.	1.4	LCS recovery outside control limits; high bias.
B	Analyte detected in associated method blank.	L-	LCS recovery outside control limits; low bias.
C	Identification confirmed by GC/MS.	M	MS recovery outside control limits; LCS acceptable.
D	Surrogates diluted out; recovery not available,	M+	MS recovery outside control limits high bias, LCS acceptable.
E	Estimated result; concentration exceeds calibration range.	M-	MS recovery outside control limits low bias; LCS acceptable.
ť:	Field measurement.	N	Analyte is not part of our NELAC accreditation.
		ND	Analyte was not detected using a library search routine; No calibration standard was analyzed.
G	Surrogate recovery outside control limits; matrix effect.	J>	Chemical preservation pH adjusted in lab.
H	Analysis or extraction holding time exceeded.	Q	The analyte was determined by a GC/MS database search.
J	Estimated result; concentration is less than calib range.	\$	Analyte was sub-contracted to another laboratory for analysis.
K	RPD outside control limits.	1	Sample temperature upon receipt exceeded 0-6°C
RL.	Routine Reporting Limit (Lowest amount that can be detected when routine weights/volumes are used without dilution.)	W	Reporting limit elevated due to sample matrix.

All quality control criteria, as outlined in the methods, have been met except as noted below or on the following analytical report.

#### Sample Batch Comments:

Sample acceptance criteria were met.



1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

#### **Analytical Report**

Client:

TESTING SERVICE CORP.

Date Collected:

05/28/10

Project ID:

61102

Time Collected:

13:30

Sample ID:

EWL-2, 2Q, 2010

Date Received:

05/28/10

Sample No:

10-2115-001

Date Reported:

06/28/10

				Date		
Analyte	Result	R.L.	Units	Analyzed	Method	Flag
Ammonia (as N)	164	0.10	mg/L	06/09/10	350.1R2.0	
COD	250	10	mg/L	06/07/10	5220D	
Cyanide, Total	< 0.005	0,005	mg/L	06/08/10	335.4R1.0	
Oil & Grease	< 1	1	mg/L	06/04/10	1664A	
рН @ 25°C	7.35		Units	05/28/10 16:30	4500H+,B	
Phosphorus (as P)	0.02	0.01	mg/L	06/08/10	4500P,B,E	
Phenols	0.014	0.010	mg/L	06/02/10	420.4R1.0	





# First Environmental Laboratories, Inc.

IL ELAP / NELAC Accreditation # 100292

1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

#### **Analytical Report**

Client: TESTING SERVICE CORP.

Project ID: 61102

Sample ID: EWL-2, 2Q, 2010

Sample No: 10

10-2115-001

Date Collected: 05/28/10

Time Collected: 13:30

Date Received: 05/28/10

Analyte		Result	R.L.	Units	Flags
Votatile Organic Compounds Analysis Date: 06/02/10	Method: 624				
Acrolein		< 100	100	ug/L	
Acrylonitrile		< 100	100	ug/L	
Benzene		6.5	5.0	ug/L	
Bromodichloromethane		< 1.0	1.0	ug/L	
Bromoform		< 1.0	1.0	ug/L	
Bromomethane		< 5.0	5.0	ug/L	
Carbon disulfide		< 5.0	5.0	ug/L	
Carbon tetrachloride		< 5.0	5.0	ug/L	
Chlorobenzene		28.3	5.0	ug/L	
Chlorodibromomethane		< 1.0	1.0	ug/L	
Chloroethane		14.1	10.0	ug/L	
2-Chloroethyl vinyl ether		< 10.0	10.0	ug/L	
Chloroform		< 1.0	1.0	ug/L	
Chloromethane		< 10.0	10.0	ug/L	
1,2-Dichlorobenzene		< 5.0	5.0	ug/L	
1,3-Dichlorobenzene		< 5.0	5.0	ug/L	
1,4-Dichlorobenzene		9.4	5.0	ug/L	
1,1-Dichloroethanc		< 5.0	5.0	ug/L	
1,2-Dichloroethane		< 5.0	5.0	ug/L	
1,1-Dichloroethene		< 5.0	5.0	ug/L	
cis-1,2-Dichloroethene		< 1.0	1.0	ug/L	
trans-1,2-Dichloroethene		< 1.0	1.0	ug/L	
1,2-Dichloropropane		< 5.0	5.0	ug/L	
cis-1,3-Dichloropropene		< 5.0	5.0	ug/L	
trans-1,3-Dichloropropene		< 5.0	5.0	ug/L	
Ethylbenzene		< 5.0	5.0	ug/L	
Methylene chloride		< 5.0	5.0	ug/L	
1,1,2,2-Tetrachloroethane		< 5.0	5.0	ug/L	
Tetrachloroethene		< 5.0	5.0	ug/L	
Toluenc		< 5.0	5.0	ug/I.	
1,1,1-Trichloroethane		< 5.0	5.0	ug/L	
1,1,2-Trichloroethane		< 5.0	5.0	ug/L	
Trichloroethene		< 5.0	5.0	ug/L	
Vinyl chloride		< 2.0	2.0	ug/L	



## Environmental Laboratories, Inc.

IL ELAP / NELAC Accreditation # 100292

1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

#### **Analytical Report**

Client:

TESTING SERVICE CORP.

Project ID:

61102

EWL-2, 2Q, 2010 Sample ID:

Sample No:

10-2115-001

Date Collected: 05/28/10

Time Collected: 13:30

Date Received:

05/28/10

Analyte		Result	R.L.	Units	Flags
Semi-Volatile Compounds Analysis Date: 06/03/10	Method: 625			Method 625 Date: 06/02/10	
Acenaphthene		< 10	10	ug/L	
Acenaphthylene		< 10	10	ug/L	
Anthracene		< 10	10	ug/L	
Benzidine		< 10	10	ug/L	
Benzo(a)anthracene		< 10	10	ug/L	
Benzo(a)pyrene		< 10	10	ug/L	
Benzo(b)fluoranthene		< 10	10	ug/L	
Benzo(k)fluoranthene		< 10	10	ug/L	
Benzo(ghi)Perylene		< 10	10	ug/L	
bis(2-Chloroethoxy)methane		< 10	10	ug/L	
bis(2-Chloroethyl)ether		< 10	10	ug/L	
bis(2-Chloroisopropyl)ether		< 10	10	ug/L	
bis(2-Ethylhexyl)phthalate		< 5	5	ug/L	
4-Bromophenyl phenyl ether		< 10	10	ug/L	
Butyl benzyl phthalate		< 10	10	ug/L	
4-Chloro-3-inethylphenol		< 20	20	ug/L	
2-Chloronaphthalene		< 10	10	ug/L	
2-Chlorophenol		< 10	10	ug/L	
4-Chlorophenyl phenyl ether		< 10	10	ug/L	
Chrysene		< 10	10	ug/L,	
Di-n-butyl phthalate		< 10	10	ug/L	
Di-n-octylphthalate		< 10	10	ug/L	
Dibenzo(a,h)anthracene		< 10	10	ug/L	
3,3'-Dichlorobenzidine		< 20	20	ug/L	
2,4-Dichlorophenol		< 10	10	ug/L	
Diethyl phthalate		< 10	10	ug/L	
2,4-Dimethylphenol		< 10	10	ug/L	
Dimethyl phthalate		< 10	10	ug/L	
4,6-Dinitro-o-Cresol		< 50	50	ug/L	
2,4-Dinitrophenol		< 10	10	ug/L	
2,4-Dinitrotoluene		< 10	10	ug/L	
2,6-Dinitrotoluene		< 10	10	ug/L	
1,2-Diphenylhydrazine (as Azobenzene)		< 10	10	ug/L	
Fluoranthene		< 10	10	ug/L	
Fluorene		< 10	10	ug/L	
Hexachlorobenzene		< 10	10	ug/L	

1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

#### **Analytical Report**

Client: TESTING SERVICE CORP.

Project ID: 61102

Sample ID: EWL-2, 2Q, 2010

Sample No: 10-2115-001

Date Collected: 05/28/10

Time Collected: 13:30

Date Received: 05/28/10

Analyte	, www.	Result	R.L.	Units	Flags
Semi-Volatile Compounds Analysis Date: 06/03/10	Method: 625		Preparation Preparation [		
Hexachlorobutadiene		< 10	10	ug/L	
Hexachlorocyclopentadiene		< 10	10	ug/L	
Hexachloroethane		< 5	5	ug/L	
Indeno(1,2,3-cd)pyrene		< 10	10	ug/L	
Isophorone		< 10	10	ug/L	
Naphthalene		< 10	10	ug/L	
Nitrobenzene		< 10	10	ug/L	
2-Nitrophenol		< 10	10	ug/L	
4-Nitrophenol		< 50	50	ug/L	
n-Nitrosodi-n-propylamine		< 10	10	ս <i>ջ/</i> Լ,	
n-Nitrosodimethylamine		< 10	10	ug/L	
n-Nitrosodiphenylamine		< 10	10	ug/L	
Pentachlorophenol		< 10	10	ug/L	
Phenanthrene		< 10	10	ug/L	
Phenol		< 10	10	ug/L	
Pyrene		< 10	10	ug/L	
1,2,4-Trichlorobenzene		< 10	10	ug/L	
2,4,6-Trichlorophenol		< 10	10	ug/L	
Pesticides/PCBs Analysis Date: 06/07/10	Method: 608		Preparation Preparation I	Method 608 Date: 06/04/10	
Aldrin		< 0.05	0.05	ug/L	
Aroclor 1016		< 0.50	0.50	ug/L	
Aroclor 1221		< 0.50	0.50	ug/L	
Aroclor 1232		< 0.50	0.50	ug/L	
Aroclor 1242		< 0.50	0.50	ug/L	
Aroclor 1248		< 0.50	0.50	цg/L	
Aroclor 1254		< 0.50	0.50	ug/L	
Aroclor 1260		< 0.50	0.50	ug/L	
alpha-BHC		< 0.05	0.05	ug/L	
beta-BHC		< 0.05	0.05	ug/L	
delta-BHC		< 0.05	0.05	ug/L	
gamma-BHC (Lindane)		< 0.05	0.05	ug/L	
alpha-Chlordane		< 0.50	0.50	ug/L	
gamma-Chlordane		< 0.50	0.50	ug/L	
Chlordane (technical)		< 0.50	0.50	ug/L	
4,4'-DDD		< 0.10	0.10	ug/L	

1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

#### Analytical Report

Client: TESTING SERVICE CORP.

61102

**Sample ID:** EWL-2, 2Q, 2010

Sample No: 10-2115-001

Project ID:

Date Collected: 05/28/10

Time Collected: 13:30

Date Received: 05/28/10

Analyte		Result	R.L.	Units	Flags
Pesticides/PCBs Analysis Date: 06/07/10	Method: 608		Preparation Preparation D		
4,4'-DDE		< 0.10	0.10	ug/L	
4,4'-DDT		< 0.10	0.10	ug/L	
Dieldrin		< 0.10	0.10	ug/L	
Endosulfan I		< 0.05	0.05	ug/L	
Endosulfan II		< 0.10	0.10	ug/L	
Endosulfan sulfate		< 0.10	0.10	ug/L	
Endrin		< 0.10	0.10	ug/L	
Endrin aldehyde		< 0.10	0.10	ug/L	
Endrin ketone		< 0.10	0.10	ug/L	
Heptachlor		< 0.05	0.05	ug/L	
Heptachlor epoxide		< 0.05	0.05	ug/L	
Methoxychlor		< 0.50	0.50	ug/L	
Toxaphene		< 1.0	1.0	ug/L	
Total Metals Analysis Date: 06/05/10	Method: 200.8R	5,4	Preparation Preparation D		
Arsenic		< 0.002	0.002	mg/L	
Barium		0.355	0.001	mg/L	
Cadmium		< 0.001	0.001	mg/L	
Chromium		0.003	0.001	mg/L	
Copper		< 0.001	0.001	mg/L	
fron		11.4	0.01	mg/L	
Lead		< 0.002	0.002	mg/L	
Manganese		0.429	0.001	mg/L	
Nickel		0.020	0,001	mg/L	
Zinc		0.011	0.005	mg/L	
Total Metals Analysis Date: 06/04/10	Method: 245.1R	3.0			-
Mercury		< 0.0005	0.0005	mg/L	
Dioxin, Low Resolution Analysis Date: 06/23/10	Method: 8280	,	. //=		
Dioxin		Attache	ed .		S



June 10, 2010

Mr. Dave Hurst TESTING SERVICE CORP.

360 So. Main Place Carol Stream, IL 60188

Project ID: 53152

First Environmental File ID: 10-2114

Date Received: May 28, 2010

Dear Mr. Dave Hurst:

The above referenced project was analyzed as directed on the enclosed chain of custody record.

All Quality Control criteria as outlined in the methods and current IL ELAP/NELAP have been met unless otherwise noted. QA/QC documentation and raw data will remain on file for future reference. Our accreditation number is 100292 and our current certificate is number 002468: effective 02/23/10 through 02/28/11.

I thank you for the opportunity to be of service to you and look forward to working with you again in the future. Should you have any questions regarding any of the enclosed analytical data or need additional information, please contact me at (630) 778-1200 or stan@firstenv.com.

Sincerely,

Stan Zaworskî

Project Manage



1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

#### Case Narrative

#### TESTING SERVICE CORP.

Project ID:

53152

First Environmental File ID: 10-2114

Date Received: May 28, 2010

Flag	Description	Flag	Description (Control of Control o
<	Analyte not detected at or above the reporting limit.	1,+	LCS recovery outside control limits; high bias.
В	Analyte detected in associated method blank.	L-	LCS recovery outside control limits; low bias.
C	Identification confirmed by GC/MS.	M	MS recovery outside control limits; LCS acceptable.
D	Surrogates diluted out; recovery not available.	M+	MS recovery outside control limits high bias; LCS acceptable.
E	Estimated result; concentration exceeds calibration range.	M-	MS recovery outside control limits low bias; LCS acceptable,
F	Field measurement.	N	Analyte is not part of our NELAC accreditation.
		ND	Analyte was not detected using a library search routine; No calibration standard was analyzed.
G	Surrogate recovery outside control limits; matrix effect,	r	Chemical preservation pH adjusted in lab.
H	Analysis or extraction holding time exceeded.	Q	The analyte was determined by a GC/MS database search.
J	Estimated result; conceutration is less than calib range.	S	Analyte was sub-contracted to another laboratory for analysis.
K	RPD outside control fimits.	T	Sample temperature upon receipt execeded 0-6°C
RL.	Routine Reporting Limit (Lowest amount that can be detected when routine weights/volumes are used without dilution.)	W	Reporting limit elevated due to sample matrix.

All quality control criteria, as outlined in the methods, have been met except as noted below or on the following analytical report.

#### Sample Batch Comments:

Sample acceptance criteria were met.

1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

#### **Analytical Report**

Client:TESTING SERVICE CORP.Date Collected:05/28/10Project ID:53152Time Collected:13:45Sample ID:EWL-2, 2010Date Received:05/28/10Sample No:10-2114-001Date Reported:06/10/10

Analyte	Result	R.L.	Units	Flags
Volatile Organic Compounds Analysis Date: 06/03/10	Method: 5030B/8260B			
Acetone	< 100	100	ug/L	
Benzene	6.2	5.0	ug/L	
Bromodichloromethane	< 1.0	1.0	ug/L	
Bromoform	< 1.0	1.0	ug/L	
Bromomethane	< 5.0	5.0	ug/L	
2-Butanone (MEK)	< 10.0	10.0	ug/L	
Carbon disulfide	< 5.0	5.0	ug/L	
Carbon tetrachloride	< 5.0	5.0	ug/L	
Chlorobenzene	27.4	5.0	ug/I_	
Chlorodibromomethane	< 1.0	1.0	ug/L	
Chloroethane	16.1	10.0	ug/L	
Chloroform	< 1.0	1.0	ug/L	
Chloromethane	< 10.0	10,0	ug/L	
I, I-Dichloroethane	< 5.0	5.0	ug/L	
1,2-Dichloroethane	< 5.0	5.0	ug/L	
1,1-Dichloroethene	< 5.0	5.0	ug/L	
cis-1,2-Dichloroethene	< 5.0	5.0	ug/L	
trans-1,2-Dichloroethene	< 5.0	5.0	ug/L	
1,2-Dichloropropane	< 5.0	5.0	ug/L	
cis-1,3-Dichloropropene	< 1.0	1.0	ug/L	
trans-1,3-Dichloropropene	< 1.0	1.0	ug/L	
Ethylbenzene	< 5.0	5,0	ug/L	
2-Hexanone	< 10.0	10.0	ug/L	
Methyl-tert-butylether (MTBE)	< 5.0	5.0	ug/L	
4-Methyl-2-pentanone (MIBK)	< 10.0	10,0	_I\gu	
Methylene chloride	< 5.0	5.0	ug/L	
Styrene	< 5.0	5.0	ug/l	
1,1,2,2-Tetrachloroethane	< 5.0	5.0	ug/L	
Tetrachloroethene	< 5.0	5.0	ug/L	
Toluene	< 5.0	5.0	ug/L	
1,1,1-Trichloroethane	< 5.0	5.0	ug/l.	
1,1,2-Trichloroethane	< 5.0	5.0	ug/L	
Trichloroethene	< 5.0	5.0	ug/L	
Vinyl acetate	< 10.0	10.0	ug/L	
Vinyl chloride	< 2.0	2.0	ug/L	
Xylene, Total	6.9	5.0	ug/L	

1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

#### **Analytical Report**

Client:TESTING SERVICE CORP.Date Collected:05/28/10Project ID:53152Time Collected:13:45Sample ID:EWL-2, 2010Date Received:05/28/10Sample No:10-2114-001Date Reported:06/10/10

Analyte	MERCHARDE DE ARRENT DE SERVICE DES TRANSPORTES DE L'ARRENT DE L'AR	Result	R.L.	Units	Flags
Semi-Volatile Compounds Analysis Date: 06/03/10	Method: 8270C			Method 351 Date: 06/03/10	
Acenaphthene		< 10	10	ug/L	
Acenaphthylene		< 10	10	ug/L	
Anthracene		< 10	10	ug/L	
Benzidine		< 10	10	ug/L	
Benzo(a)anthracene		< 10	10	ug/L	
Benzo(a)pyrene		< 10	10	ug/L	
Benzo(b)fluoranthene		< 10	10	ug/L	
Benzo(ghi)perylene		< 10	10	ug/L	
Benzo(k)fluoranthene		< 10	10	ug/L	
Benzoic acid		< 50	50	ug/L	
Benzyl alcohol		< 20	20	ug/L	
bis(2-Chloroethoxy)methane		< 10	10	ո6/Г	
bis(2-Chloroethyl)ether		< 10	10	ug/L	
bis(2-Chloroisopropyl)ether		< 10	10	ug/L	
bis(2-Ethylhexyl)phthalate		< 5	5	ug/L	
4-Bromophenyl phenyl ether		< 10	10	ug/L	
Butyl benzyl phthalate		< 10	10	ug/L	
Carbazole		< 10	10	ug/L	
4-Chloroaniline		< 10	10	սց/Լ	
4-Chloro-3-methylphenol		< 20	20	ug/L	
2-Chloronaphthalene		< 10	10	ug/L	
2-Chlorophenol		< 10	10	ug/L	
4-Chlorophenyl phenyl ether		< 10	10	ug/L	
Chrysene		< 10	10	ug/L	
Di-n-butyl phthalate		< 10	10	ug/L	
Di-n-octylphthalate		< 10	10	นย/ไ_	
Dibenzo(a,h)anthracene		< 10	10	ug/L	
Dibenzofuran		< 10	10	սք/Լ	
1,2-Dichlorobenzene		< 10	10	ug/L	
1,3-Dichlorobenzene		< 10	10	սք/Լ	
1,4-Dichlorobenzene		< 10	10	ug/L	
3,3'-Dichlorobenzidine		< 20	20	ug/L	
2,4-Dichlorophenol		< 10	10	ug/L	
Diethyl pltthalate		< 10	10	ug/L	
2,4-Dimethylphenol		< 10	10	ug/L	
Dimethyl phthalate		< 10	10	ug/L	



1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

#### **Analytical Report**

Client: TESTING SERVICE CORP. Date Collected: 05/28/10 Project ID: 53152 Time Collected: 13:45 Sample ID: EWL-2, 2010 Date Received: 05/28/10 Sample No: 10-2114-001 Date Reported: 06/10/10

Analyte		Result	R.L.	Units	Flags
Semi-Volatile Compounds Analysis Date: 06/03/10	Method: 8270C			Method 351 Date: 06/03/10	0C
4,6-Dinitro-2-methylphenol		< 50	50	ug/L	
2,4-Dinitrophenol		< 10	10	ug/L	
2,4-Dinitrotoluene		< 10	10	ug/L	
2,6-Dinitrotoluene		< 10	10	ug/L	
Fluoranthene		< 10	10	ug/L	
Fluorene		< 10	10	ug/L	
Hexachlorobenzene		< 10	10	ug/L	
Hexachlorobutadiene		< 10	10	ug/L	
Hexachlorocyclopentadiene		< 10	10	ug/L	
Hexachioroethane		< 5	5	ug/L	
Indeno(1,2,3-cd)pyrene		< 10	10	ug/L	
Isophorone		< 10	10	ug/L	
2-Methylnaphthalene		< [0	10	ug/L	
2-Methylphenol		< 10	10	ug/L	
3 & 4-Methylphenol		< 10	10	ug/L	
Naphthalene		< 10	10	ug/L	
2-Nitroaniline		< 50	50	ug/L	
3-Nitroaniline		< 50	50	ug/L	
4-Nitroaniline		< 20	20	ug/L	
Nitrobenzene		< 10	10	ug/L	
2-Nitrophenol		< 10	10	ug/L	
4-Nitrophenol		< 50	50	ug/L	
n-Nitrosodimethylamine		< 10	10	ug/L	
n-Nitrosodi-n-propylamine		< 10	10	ug/L	
n-Nitrosodiphenylamine		< 10	10	ug/L	
Pentachlorophenol		< 10	10	ug/L	
Phenanthrene		< 10	10	ug/L	
Phenol		< 10	10	ug/L	
Pyrene		< 10	10	ug/L	
1,2,4-Trichlorobenzene		< 10	10	ug/L	
2,4,5-Trichlorophenol		< 10	10	ug/L	
2,4,6-Trichlorophenol		< 10	10	ug/L	
Pesticides Analysis Date: 06/07/10	Method: 8081A		Preparation Method 3510C Preparation Date: 06/04/10		
Aldrin		< 0.05	0.05	ug/I.	
alpha-BHC		< 0.05	0.05	ug/L	



1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

#### **Analytical Report**

Client: TESTING SERVICE CORP.

Project ID: 53152

EWL-2, 2010

Sample ID: Sample No: 10-2114-001 Date Collected: 05/28/10 Time Collected: 13:45

Date Received: 05/28/10

Pesticides	04/10
delta-BHC         < 0.05	
delta-BHC         < 0.05	
gamma-BHC (Lindane)       < 0.05	
alpha-Chlordane       < 0.50	
gamma-Chlordane       < 0.50	
4,4'-DDE       < 0.10	
4,4'-DDE       < 0.10	
A,4'-DDT	
Endosulfan I	
Endosulfan I	
Endosulfan II	4
Endosulfan sulfate	
Endrin       < 0.10	
Endrin ketone	
Endrin ketone	
Heptachlor	,
Heptachlor epoxide	
Toxaphene       < 1.0       1.0       ug/L         Ammonia (as N)       Method: 350.1R2.0         Analysis Date: 06/09/10       160       0.10       mg/L         BOD, 5 Day       Method: 5210B         Analysis Date: 05/28/10 14:30       Method: 5210B	ı
Ammonia (as N)  Analysis Date: 06/09/10  Ammonia (as N)  BOD, 5 Day  Analysis Date: 05/28/10 14:30  Method: 350.1R2.0  160  0.10 mg/I	j.
Analysis Date: 06/09/10  Ammonia (as N) 160 0.10 mg/I  BOD, 5 Day Method: 5210B  Analysis Date: 05/28/10 14:30	,
BOD, 5 Day Method: 5210B Analysis Date: 05/28/10 14:30	South Opening Fords Company and Company
Analysis Date: 05/28/10 14:30	-
BOD, 5 Day 46 1 mg/L	
	-/
Chloride Method: 4500Cl, E Analysis Date: 06/08/10	
Chloride 560 5 mg/L	~
Chromium, Hexavalent Method: 3500Cr,B Analysis Date: 06/01/10 13:00	bedrach stronger to a
Chronium, Hexavalent < 0.050 0.05 mg/l	••
COD Method: 5220D Analysis Date: 06/07/10	Personne S e no universor anches : a comme com
COD 247 10 mg/I	



1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

#### **Analytical Report**

Client; TESTING SERVICE CORP.

Project ID: 53152

Sample ID: EWL-2, 2010

Sample No: 10-2114-001 Date Collected: 05/28/10

Time Collected: 13:45

Date Received: 05/28/10 Date Reported:

06/10/10

Analysis Date: 06/08/10 Cyanide, Total	Analyte	Result	R.L.	Units	Flags
Cyanide, Total         < 0.005         0.005         mg/L           Oil & Grease Analysis Date: 06/03/10 Oil & Grease         Method: 1664A         mg/L           PH @ 25°C Analysis Date: 05/28/10 16:30 pH @ 25°C         Method: 4500H+,B         mg/L           Phenois Analysis Date: 06/02/10 Phenois         Method: 420,4R1.0         mg/L           Analysis Date: 06/02/10 Phenols         0.014         9.010         mg/L           Sulfate Analysis Date: 06/02/10 Sulfate         √ 15         15         mg/L           Total Dissolved Solids Analysis Date: 06/02/10 Total Dissolved Solids Analysis Date: 06/03/10 Total Suspended Solids Analysis Date: 06/03/10 Total Suspended Solids         Method: 2540D Method: 2540D Analysis Date: 06/05/10 Analysis Date: 06/05/10 Analysis Date: 06/05/10 Analysis Date: 06/05/10 Analysis Date: 06/05/10 Arsenic         Preparation Method 3010A Preparation Date: 06/01/10 mg/L           Cotal Metals Analysis Date: 06/05/10 Arsenic         0.002 0.002 0.002 0.002 0.002 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001 0.001	Cyanide, Total	Method: 335.4R1.0	w		
Oil & Grease         Method: 1664A           Analysis Date: 06/03/10         6/03/10           Oil & Grease         < 1 1 1 mg/L	•	. 0.005	0.005	/*	
Analysis Date: 06/03/10 Oil & Grease	Cyanide, Total	< 0.005	0.005	mg/L	
Oil & Grease         < 1         1         mg/L           pH @ 25°C         Method: 4500H+,B         Analysis Date: 05/28/10 16:30         Method: 420.4R1.0         Description of the property of the prope	Oil & Grease	Method: 1664A			
PH @ 25°C   Method: 4500H+,B   Analysis Date: 05/28/10 16:30   PH @ 25°C   7.21   Units	•		,	23	
Analysis Date: 05/28/10 16:30 pH @ 25°C Phenols Analysis Date: 06/02/10 Phenols  Method: 420.4R1.0  Analysis Date: 06/02/10 Phenols  Method: 4500S04,E  Analysis Date: 06/02/10  Sulfate Analysis Date: 06/02/10  Total Dissolved Solids Analysis Date: 06/02/10  Total Dissolved Solids Analysis Date: 06/02/10  Total Suspended Solids Analysis Date: 06/03/10  Total Suspended Solids Analysis Date: 06/05/10  Arsenic	Oil & Grease	< 1		mg/L	
Phenois	pH @ 25°C	Method: 4500H+,B			
Phenois   Analysis Date: 06/02/10   Phenois   Description   Descriptio	•			*	
Analysis Date: 06/02/10   Phenols   0.014   0.010   mg/L	рН <u>@</u> 25°С	7.21		Units	
Phenols   0.014   0.010   mg/L	Phenois	Method: 420.4R1.0			
Sulfate	-			dha	
Analysis   Date: 06/02/10   Sulfate	Phenols	0.014	0.010	mg/L	announce of monthly of the sale of the sal
Sulfate   Sulf	Sulfate	Method: 4500S04,E			
Total Dissolved Solids	Analysis Date: 06/02/10				
Analysis Date: 06/02/10   Total Dissolved Solids   Z,110   10   mg/L	Sulfate	< 15	15	mg/L	
Total Dissolved Solids	Total Dissolved Solids	Method: 2540C			
Total Suspended Solids	Analysis Date: 06/02/10				
Analysis Date:         06/03/10           Total Suspended Solids         35         1         mg/L           Total Metals Analysis Date:         Method:         6010B Preparation Method 3010A Preparation Date:         06/05/10           Arsenic         < 0.002	Total Dissolved Solids	2,110	10	mg/L	
Total Suspended Solids         35         1         mg/L           Total Metals Analysis Date: 06/05/10         Method: 6010B Preparation Method 3010A Preparation Date: 06/01/10           Arsenic         < 0.002	Total Suspended Solids	Method: 2540D			
Total Metals	Analysis Ďate: 06/03/10				
Analysis Date:       06/05/10       Preparation Date:       06/01/10         Arsenic       < 0.002	Total Suspended Solids	35	]	mg/L	
Arsenic       < 0.002	Total Metals	Method: 6010B			
Barium       0.338       0.001       mg/L         Boron       1.65       0.01       mg/L         Cadmium       < 0.001	-		•	Date: 06/01/1	0
Boron         1.65         0.01         mg/L           Cadmium         < 0.001				****	
Cadmium       < 0.001					
Chromium         0.002         0.001         mg/L           Copper         < 0.001					
Copper       < 0.001				_	
lron       11.8       0.01       mg/L         Lead       < 0.002				mg/L	
Lead       < 0.002	Copper				
Manganese       0.398       0.001       mg/L         Nickel       0.019       0.001       mg/L         Selenium       < 0.002	lron			mg/ ${ m L}$	
Nickel       0.019       0.001       mg/L         Selenium       < 0.002	Lead			mg/L	
Selenium       < 0.002	Manganese	0.398	0.001	mg/L	
Selenium       < 0.002	Nickel	0.019	0.001	mg/L	
Silver < 0.001 0.001 mg/L	Selenium	< 0.002	0.002		
	Silver	< 0.001	0.001		
	Zinc	0.011	0.005		



1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

#### **Analytical Report**

Client:

TESTING SERVICE CORP.

Project ID:

53152

Sample ID: Sample No: EWL-2, 2010

10-2114-001

Date Collected: 05/28/10

Time Collected: 13:45

Date Received: 05/28/10

Analyte		Result	R.L.	Units	Flags
Chromium, trivalent Analysis Date: 06/05/10	Method: CALC				
Chromium, Trivalent		< 0.05	0.005	mg/L	
Total Metals Analysis Date: 06/04/10	Method: 7470A		W. C.		
Mercury		< 0.0005	0.0005	mg/L	

# First Environmental Laboratories, Inc.


#### CHAIN OF CUSTODY RECORD

Sca PoPD Pulses

Labor	ratories, Inc.		<u>C</u>	ompany N	ame: Z	3C					
irst Environment			<u>s</u>	reet Addre	:ss: <i>46</i>	0 S	, /	MAN	n /-	CAC.E	
600 Shore Road, Suite				ity:	CASU	L_S5	re	m		State:	Zip:61/85
laperville, Illinois 6056			P	none: Af	04622	600 g	Fax:			e-mail:	
hone: (630) 778-1200 • -mail: firstinfo@firsten					To: //			cs 5		Via: Fax	e-mail
EPA Certification #1002			S	ampled By	: <i>Y</i>	me	1 km	M	~_		
		_			R		, A	Analyses	;		
Project I.D.: P.O. #.:				/	Now You		1//	//	//		
			,	Mary	W. W	A Property of					
Matrix Codes: S =			124 1	- 7	( '(				/ /	<u>/</u>	
Date/Time Taken	Sample D		Matrix		+		<del> </del>			Comments	Lab LD.
1-28-10/113	EWL-L	2 @ 2010	-		1 -	<del></del> -	-		-		10-2114-001
				_		_	<del></del>	1			
							$\vdash$				-
				{ 			+				
	<del>-</del>			-	<del>                                     </del>		+-	<u> </u>			
				_	<del>                                     </del>		<del></del>				
									}		
		-	<del>                                     </del>	+			+	1	-		
		<u> </u>			<del>                                     </del>		<b>├</b> -	_			
			+		<del>                                     </del>	<del></del>	+				
					-		┼				
FOR LAB USE ONLY:  Cooler Temperature: 0.1  Received within 6 hrs. of the present. Yes No.	collection:	Refi 503:	nple Refrigerat rigerator Temp 5 Vials Frozen ezer Temperati	erature: : Yes N	°C					Yes No	
	d detions:	7 (	Rim	Stone	LE 1	es T	2	<u>'</u> -5-	25	4-001	
Relinguished By:	Tany Ho	Date/Ti	5/25	1/10 1	Receive		Ri	_{_	<u>,                                     </u>	Date/Time	5/28/10 1515
•			ne	•			17	1		Date/Time	-1-10
Kelinquished By: Key, 908		Date Hi	,10		1/606146	~ D _J				Date time	

#### TSC # L - 53,152

#### Mallard North Landfill- Leachate Sampling and Analysis



Note: Test methods as described in 40 CFR 136 shall be utilized for analysis.

# Attachment 3 HDPE Pipe Specifications

#### SECTION 02618 HIGH-DENSITY POLYETHYLENE (HDPE) PIPE AND FITTINGS

#### PART 1. GENERAL

#### 1.1 SECTION INCLUDES

A. Providing High Density Polyethylene (HDPE) Pipe, fittings and appurtenances for leachate piping as indicated on Drawings.

#### 1.2 REFERENCES

- A. ASTM D4976 Polyethylene plastics molding and extrusion materials
- B. ASTM D3350 Standard specification for polyethylene plastic pipe and fittings materials.
- C. ASTM D3261 Butt fittings for HDPE pipes.
- D. ASTM D2513 Industrial molded fittings for HDPE pipes.
- E. ASTM D2683 Socket fittings for HDPE pipes

#### 1.3 QUALITY CONTROL REQUIREMENTS

- A. Prior to delivery of piping to the site, the Piping Manufacturer will provide the following information:
  - 1. Resin supplier's name, location of supplier's production plant(s), and the resin brand name and product number.
  - Test results obtained by the piping manufacturer and/or the piping manufacturer's testing laboratories to document the quality of the resin used in manufacturing the piping.
  - 3. Quality Control Plan that the piping manufacturer will be using fort the pipe being supplied.
- B. The Piping Manufacturer will provide certification, based on test results, that:
  - 1. Pipe supplied meets all Material Specifications in Section 02618 2.2.
  - Finished pipe meets the cell classification of 345434C according to the provisions of ASTM D3350
  - 3. Finished pipe has the SDR value specified.

#### 1,4 DELIVERY, STORAGE AND HANDLING

- A. Each bundle of pipe prepared for shipment by the Piping Fabricator will be marked with the following information:
  - Nominal size
  - 2. Dimension ratio

- 3. Pressure rating
- 4. Type (manufacturer)
- 5. Material classification
- Protect pipe during shipment from excessive heat or cold, puncture, or other damaging or deleterious conditions.
- C. Protect pipe on-site from long-term ultraviolet exposure, the elements, weather changes, and construction activities.
- D. Store materials in areas that are safe from construction activities.

#### 1.5 SUBMITTALS

A. Provide data on pipe materials, pipe fittings, and accessories.

#### PART 2. PRODUCTS

#### 2.1 ACCEPTABLE MANUFACTURERS/SUPPLIERS

- A. Pipe and Valves:
  - Plastic Fusion Fabricators
     3455 Stanwood Blvd.
     Huntsville, AL 35811
     800/356/1480
  - Michigan Supply Company
     631 Park Place
     Lansing, MI 48901
     517/484/6444
  - 3. Isco Industries 926 Baxter Avenue Louisville, KY 40204 800/345/4726
  - Forrer Supply Company, Inc.
     W194 N11811 McCormick Drive
     Germantown, WI 53022
     800/255/1030

#### 2.2 MATERIALS

- A. Only new and undamaged materials shall be used.
- B. HDPE pipe and fittings shall be made from high-density, extra high molecular weight material with a broad range molecular weight distribution designated as PE 3408 with an ASTM D3350 cell classification number of 345434C.
- C. SDR 17 HDPE piping: 2, 3, 4, 6, 8, and 10-inch diameter, complete with bends, fittings, and appurtenances, as shown on the Drawings.

D. Joints: Heat fusion process according to manufacturer's specifications.

#### PART 3. EXECUTION

#### 3.1 INSPECTION

- Inspect pipe, fittings, and other appurtenances before installation to verify quality of material.
- B. Bends to be prefabricated in the field, prefabricated, or made by bending straight sections of pipe.

#### 3.2 PREPARATION

- A. Ream pipe and tube ends. Remove burrs.
- B. Remove dirt and foreign material, inside and outside, from pipe and fitting materials before assembly.
- C. Make straight field cuts without chipping or cracking the pipe.

#### 3.3 BEDDING

A. As shown on the Drawings.

#### 3.4 INSTALLATION

- A. Pipe seams: Make heat fusion joints in accordance with the manufacturer's specifications.
- B. Install pipe and fittings to the line and grade specified on the Drawings.
- C. Lay pipe from the low end toward the high point. Provide continuous smooth invert.
- D. Pipe placement will not be performed in the presence of excessive moisture or when the underlying prepared surface has deteriorated since previous acceptance.
- E. Maximum allowable tolerance for grade is 0.10 foot.
- F. Install bedding and backfill material over pipe as designated in the drawings with care to avoid damage to pipe. Minimize traffic and turning of traffic over pipe.

#### 3.5 FIELD QUALITY CONTROL

- A. ENGINEER to observe pipe subgrade installation, and pipe installation prior to backfilling.
- B. When fusing joints and fittings, follow supplied manufacturer's directions and procedures for heat jointing pipes and fittings.
- C. CONTRACTOR shall air pressure test all solid-wall HDPE leachate piping in the presence of the ENGINEER.
- D. Gravity pipe pressure testing shall consist of applying a pressure of 5.5 psig for a minimum of 30 minutes with less than a 5 percent decrease in pressure.

- E. Test forcemain pipe at a pressure of 40 psig for a minimum of 30 minutes with less than a 5 percent decrease in pressure.
- F. Pipe inverts and coordinate locations will be surveyed at 50-foot intervals and at all tee connection locations.
- G. Flush pipe with sewer cleaning equipment when construction is completed, prior to final acceptance.

**END OF SECTION** 

# Attachment 4 Lift Station Calculations



#### COMPUTATION SHEET

#HIP#				SIDEET	1	OF3
744 Heartland Traff (53717-8923) P. O. Box	8923 (53708-8923)	Madison,	WI (608) 831-	4444 FAX:	(608) 831-3334	VOICE: (608) 831-1989
PROJECT/PROPOSAL NAME	PREPARED		CHECKED		PROJECT/PRO	OPOSAL NO.
Mallard North Landfill Leachate	By: J. Kucher	Date: 12/7/10	By: JRS	Date: 12/8/10		01793.04.001
Force Main Connection	ŀ					

#### LEACHATE LIFT STATION DESIGN

#### Purpose:

To collect leachate from the Mallard North Landfill and pump the leachate to the Village of Hanover Park sanitary sewer forcemain.

#### **Assumptions:**

- Lift station to replace existing above grade frac tank.
- Leachate enters the concrete lift station from the three pneumatic leachate pumps through a 4-inch-diameter (SDR 17) HDPE pipe (encased with a 8-inch-diameter HDPE [SDR 17] pipe outside of landfill limits) at approximately 12 to 20 gpm.
- Design flow from lift station to HP FM is 40 to 50 gpm at approximately 55 feet of head.
- Lift station to include two submersible electric pumps; alternating, controlled by float switches; electrical control panel above-grade with SCADA system.
- No solids present in leachate, little or no grit.
- 4" Quick connect pipe at vault next to lift station for tank truck loadout.
- Existing forcemain is 16-inch-diameter ductile iron pipe (D.I.P.) Thickness Class 52;
   approximately located at Station 140+00; maximum pressure is 19.8 psi (or 45.7 feet).
- Discharge metered by non-resettable flow meter.
- Dual encased piping secured to western bridge beam. Penetrate bridge abutments through wooden area. Heat trace and insulate piping.
- Above-grade electrical control panel will communicate by radio with existing Northwest Flare panel.
- Confined space entry required for lift station.



#### **COMPUTATION SHEET**

				SHEET	2	_ OF <u>3</u>
744 Heartland Trail (53717-8923) P. O. Bo	x 8923 (53708-8923)	Madison	, WI (608) 831-	4444 FAX:	(608) 831-3334	VOICE: (608) 831-1989
PROJECT/PROPOSAL NAME	PREPARED		CHECKED		PROJECT/PR	OPOSAL NO
Mallard North Landfill - Leachate	By: J. Kucher	Date: 12/7/10	By: JRS	Date: 12/8/10		01793.04.001
Force Main Connection						

#### Methodology:

#### Check Depth / Volume Relationship

6 foot diameter wet well,

Volume =  $\pi(3)^2$  1 ft (7.48 gal/cf) = 211 gal/vertical foot

DEPTH* (feet)	OPERATIONAL VOLUME (gal)	FLOW (gpm)	PUMP RUN TIME (V/gpm)
1	211	40	5.3 min.
2	422	40	10.6 min.
3	633	40	15.8 min.
4	844	40	21.1 min.
6	1,266	50	25,3 min.

#### Notes:

From pump data, Grundfos model 40S10-3, 1.03 hp, single phase, 4 inch diameter, and system head curve, the pump will operate at approximately 40 gpm at 61 feet of head. Assume 3 vertical feet (633 gallons) between pump on and pump off floats. At 40 gpm, the wet well will be drained to the pump off float in 21.1 minutes (longer if the pneumatic pumps are operating).

#### Check Buoyant Stability

#### Assumptions:

- Depth to water = 0 ft bgs.
- $\gamma_{\text{concrete}} = 150 \text{ lb/ft}^3$ ,  $\gamma_{\text{water}} = 62.4 \text{ lb/ft}^3$ ,  $\gamma_{\text{soil}} = 120 \text{ pcf.}$
- Skin friction not included.
- A FS = 1.3 is acceptable for resistance to uplift.
- Manhole is empty, weight of pump, etc., not included.
- Lift station is a 6 foot internal diameter concrete structure.
- The lift station manhole is stable when the structure weight is greater than the weight of water displaced.

Depth above dead storage (pump height or approximately 24 inches).



#### **COMPUTATION SHEET**

			SHEE	Т3	_ OF3
744 Heartland Trail (53717-8923)	P. O. Box 8923 (53708-8923)	Madison, WI	(608) 831-4444	FAX: (608) 831-3334	VOICE: (608) 831-1989

PROJECT/PROPOSAL NAME	PREPARED		CHECKED		PROJECT/PROPOSAL NO.
Mallard North Landfill – Leachate Force Main Connection	By: J. Kucher	Date: 12/7/10	By: JRS	Date: 12/8/10	01793.04.001

#### **Buoyant Force**

Weight of water displaced,

F_{buoyant} = 
$$62.4 \text{ #/cf } (\pi(3)^2)(773-762.5)$$
  
=  $18,500 \text{ lbs}.$ 

#### **Ballast Force**

Manhole weight,

= 
$$\pi 6 (0.5) (774-763) (150) = 15,551$$
lbs.

Soil above 2 foot wide perimeter wings at a 6 foot depth

= 
$$6 \text{ ft } (\pi 6) (2') (120-62.4)$$
  
=  $13,028 \text{ lbs.}$ 

#### **Check Factor of Safety**

$$F.S. = \frac{ballast force}{buoyant force} = \frac{15,551+13,028}{18,500} = \underline{1.5}$$
 Therefore ok

90

100

110

55 55

55

9.19

10.21

11.23

PROJECT NAME:	Mallard North Lift	Station	STATIC HE		55	19,8 psig (45.7	ft) +9.6 ft (vertical li
PROJECT NO.	6809.04.005		LOW FLO		20		
DATE:	12/06/10	1	INCREME	NT:	10	input in yellow	
BY:	J. Kucher	1					
CHECKED:	JRS	file P:\6809\04\	leachate fm\calcula	itionsljck lift stati	on model.xls	Truck:	
Segment No.		1				14.5 ft (pump to	ground surf) + 13.:
Pipe Material		PVC					
"C" Value		150	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
Inside Diameter		2.000					
DESCRIPTION	L/d	ату.	EQU. LENGTH	QTY.	EQU. LENGTH		
Horizonfal run	1	65	65		Q.		
Verlical Run	1	55	55		0		
Anti-siphon Valves		Q	0				
Gate	<u></u> 13	1	2		0		
Butterfly	20	1	3		0		
Check (swing)	135	0	0		0		
Check (ball)	150	2	50		0		
Elbows					***************************************		
Standard 90	30	3	15		0		
Standard 45	16	0	Q		0		
Standard 22 1/2	10	0	0		Ũ		
Standard 11 1/4	6	0	0		0		
Long radius 90	20	0	<u> </u>		Ø		
Tees					***************************************		
Thru flow	20	0	0	* ****	Q		
Branch flow	60	1	10		0		
Miscellaneous	meter	1	2		0		
TOTAL EQUIVALENT LENGTH	S		203		0		
STATION		SEGMENT NO	O. 1	SEGMENT N	0, 2	TOTAL	PUMP HEAD 4" Grundfos
DISCHARGE	STATIC	1	DYNAMIC		DYNAMIC	SYSTEM	Submersible
(GPM)	HEAD	VELOCITY	HEAD	VELOCITY	HEAD	HEAD	40S10-3
	<i>a</i> r				7.7A	2 A2 A	
20	56	2.04	1.74	0.00	0.00	57.04	73
30	<u>55</u>	3.06	3.69	0.00	0.00	58.99	67
40	55 56	4.08	6.29	0.00	0.00	61.59	62
50	55	511	9.50	0.00	0.00	64.80	51
60	55 rc	6.13	13.31	0.00	0.00	68.61	
70 80	55 55	7.15 8.17	17.71 22.67	0.00	0.00	73.01 77.97	***************************************
δυ αα	50 65	0.17	24.07 28.40	0.00	ሳው. ስ ስስ	97.97	

0.00

0.00

0.00

22.67 28.19

34.25

40.86

0.00

0.00

0.00

83.49


89.55

96.16

ift) =

5 ft i

## MALLARD NORTH LANDFILL LEACHATE LIFT STATION






Company name: DUFF CO.
Created by: PAUL ROSEN
Phone: 610-275-4453
Fax: 610-279-6299

**Fax:** 610-279-6299 **Date:** 12/07/2010

#### 11890003 40\$10-3



上からの海木 たるやお

		Hanover Park, Illinois 40527
	ENGINEERS	Mallard Lake Leachate Connection SHEET
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	CONSOER TOWNSEND ENVIRODYNE ENGINEERS, INC.	SUBJECT LARE LEAGUE CONTRACTON SHEET
	[E] (###4##21 E) (#44 ( ) () (## ( ) () () () () () () () () () () () ()	RJK 11/05/04 CHECKED DATE
		(A)
	TAXE STATE OF THE	
		7
	WAYX	
	000 000 000 000 000 000 000 000 000 00	WAXI HOLL
	THE PARTY OF THE P	
! !		
	₹ <b>8</b> - 1   1   1   1   1   1   1   1   1   1	
	00 988 H Q H	
<u> </u>	A CONTRACTOR OF THE CONTRACTOR	
		BAY SIDE
<i>i</i>		BAYSIDE PUMP
		A - NOIL AND I - ELEVATION - 18
		J- Northy - E
	[	The Charles of Little Control of the

AP-4 Manual

# OLD Environmental System

# This is How it Works

The AutoPump is a submersible compressed alr-driven pump which tills and empties automatically. It also controls the fluid lovel in a well automatically. The pump fills (see Figure 1) when fluids enter either the top or bottom check valve. Air in the pump clamber exits through the exhaust valve as the fluid fills the pump. The fluit inside the pump is carried upwards by the fluids rising in the casing until it pushes against a stop on the control red, forcing its valve rechaudion to switch to the discharge mode.

The switching of the valve causes the exhaust valve to close and the air intervalve to open. This causes the pump to empty (see Pigare 3) by allowing compressed air to enter the pump. This pressure on the fluid closes the inlet check valve and forces the fluids up the discharge fube and out of the pump through the outlet check valve. As the fluid level faits in the pump, the float moves downwards until it pushes against the lower stop on the control rod, forcing the valve mechanism to switch to the fill mode. The outlet check valve closes and prevents discharged fluids from re-entering the jump. The filling and discharging of the pump continues automatically.

Note: The figures shown here are simplified schematics.

# Major AutoPump Features.

- The AutoPomp System is small and lightweight and can be easily moved from airc to site, allowing quick response to changing conditions.
- The hoses are color coded and all the littings are different so only the proper connections can be made.
- Rugged construction ensures long system life, even under harsh conditions.
- The entire system is pileumatically powered with no electrical components, thus avoiding sparks in control power and senting devices.
- Dwrabbe strainless steel air valves that can pass liquids as viscous as 90 weight grar oil
  without fouring. The air valves can handle triverse flow and submersion for long periods
  of time. Unlike pumps with buildhers or bleed hoses, there are no problems with sart up,
  clogging, and faiture under those difficult conditions when using the AP-4. This results in
  less downtime and lower training, maintenance, and repair costs.

# Chapter 2: Overview

The AutoPump® fills and empties automatically, and is very easy to install, use, and staintain.

The AutoPrinty is a presumatic fluid extraction many that parities in pulses. It handles any liquid which flows freely into the pump and is compatible with the component materials and with the competing hoses. The AP-4 is intended for vertical operation in well entirigs with a 3.75-and) or greater internal danaster. It can pump particles up to 1/8-incli in diameter.

The AutoPump is very versatile and available in a wide range of lengths, valve arrangements, and materials of construction to meet particular site specifications.

Equipment will vary by application and site specifications. (See Chapter 3)

# General Specifications


Pump Diameter	3.50 inch	88.9 mms
Pressure Range	5 120 pti	0.4 - 8.5 Kg/cm ²
High Pressure Option	5 - 200 psi	0.4 - 14.1 Kgicm²
Flow Ranges	G-18 guitoris per minute	0-50 Stors per minute

è

Pers

AN RELATED TO THE ACTUAL TO STATE AND ADDRESS OF THE PROPERTY AND ADDRESS OF THE PARTY AND ADDRE

PROJECT NAME: JOB NO.: DATE:	JOB NO. 1			TIC HEAD: LOW PLOW: NCREMENT:	10 2 10			
DESIGNER: FILE:	J. Kucher		PH	EVMAT				
Segment No Pipe Material "C" Value Inside Diameter		150 pvc 2.000		150 HDPE 1 000				
DESCRIPTION	L/d	QTY.	EQU.	QTY.	EQU. LENGTH			
		·						
Horizontal run	3	800	800	0	0			
Vertical Run	1	20	20	0	۰			
/alves			1					
Cate	1 13	į.	0	1	1 0	I		
Butterfly	20	l or	0	1	0			
Check (swing)	135	1	23	1				
Check (ball)	150				0			
Elbows	1		i	ri .	1			
Standard 90	30	3	15	1	0	1		
Standard 45	16	1	0	0	0	1		
Standard 22 1/2	10	1	1 0	1	0	i		
Standard 11 1/4	6	1	0	1	0			
Long radius 90	20		0		. 0			
Tees	1					i		
Thru flow	20	i		i	1 0	i		
Branch flow	60	į	0	j	0	i		
Miscellaneous	meter		2		0			
						!		
TOTAL EQUIVALENT LENG		Lapue e e e e e	860		0			
************		SEGMENT NO. 1		SEGMENT NO. 2		*********	INPUT	TOTAL
STATION	1	- DEGMENT		1 Manual		TOTAL	pump info	A. Sensis Spart Co.
DISCHARGE	STATIC		DYNAMIC		DYNAMIC	SYSTEM	poop anto	HEAD
(GPM)	- P P P P P P P P.	VELOCITY		VELOCITY		HEAD	į.	CHECK
				*******				*******
2	1 10	0.20	0.10	0.00	0.00	10.10	17	
12	10	1.23	2.88	0.00	0.00	12.88	17	
22	10	2.25	8.83	0.00	0.00	18.83	17	
32	1 10	3,27	17.66	0.00	0.00		* Table 1	
42		4.29	29.21	0.00	0.00	39.21	17	
52 62	1 10	5.31	1 60.04	0.00	0.00	70.04	16	
72	1 10	7.35	79.17	0.00	0.00	89.17	15	
82	1 10	8.37	1 100.71	0.00	0.00	110.71	1 14	
92	1 10	9.40	1 124.60	0.00	0.00	134.60	1	
94	1 20		1 204.00		0.00	234.00	1 marian de la constante de la	la company of the control of the con




## AP4B Bottom Inlet, Short

## AutoPump®


PHEUMATIC PUMES

#### Flow Rates






#### 1 inch (25.4 mm) Inside Diameter Discharge Hose (Equivilant to 1.25-Inch O.D. Tubing)



FLOW RATES MAY VARY WITH SITE CONDITIONS, CALL OED FOR TECHNICAL ASSISTANCE.









#### Air Consumption







STANDARO CUBIC FELF OF AIR GALLON PUMPED ischigat.

GRADIGATE

(SCF/GAL)

24.18

## 

#### Confide to Autorump Stelepton

#### Quick Guide to AutoPump Selection

An important advantage of an AutoPump system is the wide range of choices to truly match site needs. Below is a quick guide to the major configurations and options offered in the AutoPump line, to help you determine which models are best for your project. Of course, you can just call us at 1-800-624-2026, or email us at info@qedenv.com, for fast, personal service by our application specialists.

As a general guideline, pump model selection is usually based on the following primary application criteria. They are presented in the common sequence of consideration, but special site needs may alter the priority.

- Maximum flow and depth-pump model, depth, submergence and drive pressure determine the maximum flow rate that can be achieved; see specific pump curves for detailed flow information
- Pump Diameter- to fit the well ID; also, larger diameter pumps deliver higher flow rates, all other factors being equal
- Inlet Position- top or bottom inlet; a top inlet enhances removal of LNAPLs, while bottom inlets provide the highest flow rates and greatest solids-handling capacity for DNAPL, dissolved and landfill fluids
- Actuation Level- minimum height of liquid needed to actuate the pump, also equal to the minimum drawdown level; low-drawdown models are optimized for maximum drawdown
- Materials of construction- many models are available in upgraded materials for special applications, such as extremes of pH, suspended solids, high temperatures and aggressive solvents

AutoPumps	Model	Pg#	Inlet Position	O.t. Diameter in/cm	Overall Length in/cm	Max. Flow gpm/lpm	Max. Depth ft/m	Act. Level in/cm	
4" Bottom Inlet AP Pumps Long AP4-Bottom Inlet Short AP4 Bottom Inlet Low Drawdown AP4-Bottom Inlet	Long AP4B Short AP4B LD AP4B	6 10 14	Bottom Bottom Bottom	3.5 / 8.9 3.5 / 8.9 3.5 / 8.9	53 / 135 41 / 104 28 / 71	14 / 53 13 / 49 7 / 26.5	425 / 130 ² 425 / 130 ² 250 / 76	35 / 89 27 / 69 13 / 33 ³	
4" Bottom Inlet HammerHead Pro Pumps HammerHead Pro-Bottom inlet Short HammerHead Pro-Bottom Inlet	Long HHP48 Short HHP48		Bottom Bottom	3.5 / 8.9 3.5 / 8.9	51/130 39/99	13.5/51.I 13/49	250 / 76 250 / 76	33 / 83.8 21 / 53.3	
4" Top Inlet AP Pumps Long AP4-Top Inlet Short AP4-Top Inlet Low Drawdown AP4-Top Inlet	Long AP4T Short AP4T LD AP4T	26 30 34	Top Top Top	3.5 / 8.9 3.5 / 8.9 3.5 / 8.9	57 / 145 42 / 107 29 / 74	10/38 9/34 6.4/24	425 / 130 ² 425 / 130 ² 250 / 76	52 / 132 37 / 94 24 / 62	
4" Top Inlet HammerHead Pro Pumps HammerHead Pro-Top Inlet Short HammerHead Pro-Top Inlet	Long HHP4T Short HHP4T	38 42	Тор Тор	3.5 / 8.9 3.5 / 8.9	56/142.2 44/111.7	9.8 / 37.1 8.3 / 31.4	250 / 76 250 / 76.2	53 / 134.6 41 / 104.1	
3" Bottom Inlet AP Pumps Long AP3-Bottom Inlet Short AP3-Bottom Inlet	Long AP3B Short AP3B	46 50	Bottom Bottom	2.63 / 6.68 2.63 / 6.68	52 / 132 42 / 107	7.3 / 27.6 6 / 22.7	220 / 67 175 / 53.3	31 / 79 22 / 56	
3"Tap Inter AP Pumps Long AP3-Tap Intet Short AP3-Tap Intet	Long AP3T Short AP3T	54 58	Top Top	3.4 / 8.64 ¹ 3.4 / 8.64 ⁴	57/145 47/119	5.4 / 20 4.8 / 18.1	220 / 67 175 / 53.3	53 / 135 42 / 107	
2" Bottom Inlet AP Pumps Long AP2-Bottom Inlet Short AP2-Bottom Inlet	Long AP2B Short AP2B	62 66	Bottom Bottom	1.75 / 4.45 1.75 / 4.45	55 / 139 33 / 85	2.3 / 8.82 2 / 7.57	300 / 91.4 300 / 91.4	35 / 89 20 / 51	
2" Top Inlet AP Purups Long AP2-Top Inlet Short AP2-Top Inlet	Long AP2T Short AP2T	70 74	Top Top	1.75 / 4.45 1.75 / 4.45	57 / 144 35 / 89	1.9 / 7.2 1.6 / 6.0	300/91.4 300/91.4	52 / 132 31 / 78	

¹Consult QED for higher flow requirements



² High Pressure Option for 4" AP pumps

^{*}Optional radial inlet model provides 11.5" / 29 cm actuation level

¹ Optional 2.63" (6.68cm) OD available

Attachment 5

Figures

